

DGCA NO	SUBJECT	REFERENCE	COMPLIANCE	APPLICABILITY
DGCA/GULF STREAM -IV/1	TO PREVENT INTERFERENCE & CHAFING BETWEEN THE ALTERNATOR POWER FEEDER CABLES & ADJACENT STRUCTURE	FAA AD 2000-07-25	'AS IN AD'	'AS IN AD'
DGCA/GULF STREAM -IV/2	TO PREVENT LOSS OF HYDRAULIC SYSTEM FLUID	FAA AD 2001-08-13	'AS IN AD'	'AS IN AD'
DGCA/GULF STREAM -IV/3	TO PREVENT FIRE EXTINGUISHING AGENT FROM BEING DISCHARGED INTO THE WRONG LOCATION	FAA AD 2001-26-07	'AS IN AD'	'AS IN AD'
DGCA/GULF STREAM -IV/4	TO ENSURE THAT THE FLIGHTCREW IS AWARE THAT AN ELECTRICAL SYSTEM FAILURE HAS OCCURRED AND THAT THE AIRPLANE MAIN BATTERIES ARE POWERING THE ESSENTIAL DC BUS	FAA AD 2004- 08-08	'AS IN AD'	'AS IN AD'
DGCA/GULF STREAM -IV/5	TO DETECT AND CORRECT BROKEN DAMPER SHAFTS, WHICH COULD RESULT IN LOCKING OF AN AILERON OR ELEVATOR ACTUATOR.	FAA AD 2004-21-03	'AS IN AD'	'AS IN AD'
DGCA/GULF STREAM -IV/6	TO PREVENT SHORT CIRCUITING OF THE FLOOR HEATER PAD SYSTEM	FAA AD 2005-16-14	'AS IN AD'	'AS IN AD'
DGCA/GULF STREAM -IV/7	TO ENSURE THAT THE FLIGHTCREW IS ADVISED OF THE APPROPRIATE PROCEDURES TO FOLLOW EVEN THAT THE COCKPIT DISPLAY GO BLANK OR MALFUNCTION	FAA AD 2006-04-13 R1	'AS IN AD'	'AS IN AD'
DGCA/GULF STREAM -IV/8	TO PREVENT LEAKAGE FROM FAILED WATER DRAIN/SUPPLY VALVES ALLOWING THE BUILD UP OF ICE ON THE AIRPLANE	FAA AD 2007-12-25	'AS IN AD'	'AS IN AD'
DGCA/GULF STREAM -IV/9	TO PREVENT THIS FLAMMABLE SEALANT FROM IGNITING THE EXTERIOR SURFACES OF THE APU ENCLOSURES(FIREWALL) UNDER CERTAIN ANOMALOUS CONDITIONS SUCH AS AN APU FAILURE /APU COMPARTMENT FIRE	FAA AD 2009-17-01	'AS IN AD'	'AS IN AD'
DGCA/GULF STREAM -IV/10R1	AIRBORNE AUXILIARY POWER --- AUXILIARY POWER UNIT (APU) ENCLOSURE (FIREWALL) --- INSPECTION / LIMITATION	EASA AD 2009 - 0180R1	'AS IN AD'	'AS IN AD'