

DGCANO	SUBJECT	REFERENCE	COMPLIANCE	APPLICABILITY
DGCA/HS 748/01	INTRODUCTION OF CABLE RETAINING CLIPS TO UNITER SILEMENT CABLES	H.S.748 S.B. NO.61/3	AS IN SB	AS IN SB
DGCA/HS 748/02	INTRODUCTION OF SAFETY STOP ON ELEVATOR SERVO MOTOR MOUNTING	HS 748 SB. NO. 32/1	AS IN SB	AS IN SB
DGCA/HS 748/03	GUST LOCK IMPROVEMENT TO CONTROL SURFACES LOCK CIRCUIT	HS 748 SB. NO. 27/12	AS IN SB	AS IN SB
DGCA/HS 748/04	INTRODUCTION OF A PACKING WASHER ON PROPELLER CONTROL UNIT PLUGS	HS 748 SB NO. 61/2	AS I N SB	AS IN SB
DGCA/HS 748/05	INTRODUCTION OF A STRENGTHENED RETRACTION JACK PIN	HS 748 SB NO. 32/13	AS I N SB	AS IN AB
DGCA/HS 748/06	INCREASE OF CLEARANCE BETWEEN THE RUDDER SPRING TAB AND TAIL CONE	HS 748 SB NO. 27/16	AS I N SB	AS IN SB
DGCA/HS 748/07	BONDING OF ACCESS PANELS TO WING STRUCTURE	HS 748 SB NO. 57/3	AS I N SB	AS IN SB
DGCA/HS 748/08	TAIL PLANE CONSTRUCTION JOINT INTRODUCTION OF EXTRA RIVETS	HS 748 SB NO. 55/4	AS I N SB	AS IN SB
DGCA/HS 748/09	INTRODUCTION OF A TURN AND SLIP INDICATION- CO PILOTS PANEL	HS MOD/INDIA/HS 748/11	AS IN MOD	AS IN MOD
DGCA/HS 748/10	INSPECTION OF ELEVATOR CONTROL LEVER ASSEMBLY PT. NO. 298/G3096 FOR DAMAGE	HS 748 SB NO.A27/7	AS I N SB	AS IN SB
DGCA/HS 748/11	LOCKING OF CHAIN NUTS IN TRIM CONTROL CHAINS.	HS 748 SB NO. 27/1	FORTHWITH	AS IN SB
DGCA/HS 748/12	INSPECTION OF CROSSFEED PIPE FOR CRACKS AT WELD SEAM.	HS 748 SB NO. 28/8	FORTHWITH	AS IN SB
DGCA/HS 748/13	SECURITY OF REMOVABLE HUB PT. NO.UC 3012312 IN NOSE LANDING GEAR.	HS 748 SB NO.A32/9	FORTHWITH	AS IN SB
DGCA/HS 748/14	INSPECTION OF MAIN UNDER CARRIAGE CROSS BEAM PT. NO. UC 702501.	HS 748 SB NO. 32/12	FORTHWITH	NOT REQUIRED WHEN HS 748 SB NO. 32/13 HAS BEEN COMPLIED WITH
DGCA/HS 748/15	INSPECTION AND RECTIFICATION OF ATTACHMENT (INCORPORATION OF MOD. 1281) OF L/G EMERGENCY SYSTEM PULLEY BOSS PT. NO. 106/D 11349.	HS 748 SB NO. A32/17	FORTHWITH	AS IN SB
DGCA/HS 748/16	WEATHER RADAR INSTALLATION.	HS 748 SB NO. 34/10	FORTHWITH	AIRCRAFT WITH WEATHER RADAR
DGCA/HS 748/17	INSPECTION OF EMERGENCY EXIT PANELS FOR CORRECT FIT.	HS 748 SB NO. 52/21	FORTHWITH	AS IN SB
DGCA/HS 748/18	LIFE LIMITATION OF NOSE LANDING GEAR RETRACTION JACK MOUNTING BOLT DUE TO FATIGUE	HS 748 SB NO. 53/16	FORTHWITH	AS IN SB
DGCA/HS 748/19	LIFE LIMITATION OF NOSE LANDING GEAR RETRACTION JACK MOUNTING BRACKET DUE TO FATIGUE	HS 748 SB NO. 53/18	FORTHWITH	AS IN SB
DGCA/HS 748/20	INSPECTION OF JACK MOUNTING BRACKET	HS 748 SB NO. 54/7	FORTHWITH	AS IN SB
DGCA/HS 748/21	INSPECTION OF ENGINE MOUNTING FRAME FOR CORROSION	HS 748 SB NO. 71/2	FORTHWITH	AS IN SB
DGCA/HS 748/22	INSPECTION OF ENGINE CONTROL ABLES ON ALL FAIR LEADS FOR THROTTLE AND H.P. COCK MOUNTED ON FRONT.	HS 748 SB NO. A76/1 REV. 3 (HAS MOD. 18/66)	FORTHWITH	AS IN SB
DGCA/HS 748/23	INSPECTION OF CONNNECTIONS AT PLESSY CIRCUIT BREAKERS 7CZ/106664/50B.	HS 748 SB NO. 24/25	FORTHWITH	AS IN SB
DGCA/HS 748/24	INTRODUCTION OF A RESTRICTING BRACKET ON THE ELEVATOR CONTROL LEVER	HS 748 SB NO. 27/33	TO BE COMPLIED WITH BY 31/3/68	AS IN SB
DGCA/HS 748/25	DISCONNECTION OF FUEL TANK VENT PIPE	HS 748 SB NO. 28/7	AS IN SB	AS IN SB
DGCA/HS 748/26	FUSELAGE FORMER 18 F, FITTING OF REINFORCING ANGLES.	HS 748 SB NO. 53/12	AS IN SB	AS IN SB
DGCA/HS 748/27	INTRODUCTION OF REINFORCING PLATE AROUND THE NAVIGATION WINDOW.	HS 748 SB NO. 53/15	AS IN SB	AS IN SB
DGCA/HS 748/28	REPLACEMENT OF FUEL VENT LINES.	HS 748 SB NO.57/13	AS IN SB	AS IN SB
DGCA/HS 748/29	CORRECT FITMENT OF FUSE NO. 164 IN FLAP MOTOR SUPPLY.	HS 748 SB NO. A24/26	AS IN SB	AS IN SB
DGCA/HS 748/30	POSITIVE LOCKING OF OIL METERING UNIT IN GODFREY CABIN SUPERCHARGER.	GODFREY SB NO. 21/116	AS IN SB	AS IN SB

DGCA/HS 748/31	INTRODUCTION OF SUPPORT PLATE FOR RETRACTION JACK PIN.	DOWTY ROTOL SB NO. 32-20E	AS IN SB	AS IN SB
DGCA/HS 748/32	CANCELLED VIDE LETTER NO. 9-433/84 DT. 15/5/84 VIEW OF DGCA/HS 748/120			
DGCA/HS 748/33	INSPECTION OF FLAME IN ALTIMETER AND MODIFICATION THEREOF.	DOWTY ROTOL SB NO. 24-299	INSPECTION AS IN PT. 1, AMMEDIATELY AND INCORPORATION OF MOD NO. 45468 AS IN PART 2 BY NEXT OVERHAUL OF ALTIMETER.	AS IN SB
DGCA/HS 748/34	CHECK TO ENSURE CORRECT OPERATION OF INTERNAL REFUELLING RESTRICTER VALVE	HS 748 SB NO. 28/23	AS IN SB	INSPECTION MAY BE TERMINATED IF ACTION CALLED IN PARA "C" IS ACCOMPLISHED.
DGCA/HS 748/35	INSPECTION AND RECTIFICATION TO AVOID FOULING OF BODY OF FIRE EXTIGUISHER WITH BAFFLE PLATE IN ENGINES NACELLE.	HS 748 SB NO. 26/6	AS IN SB	AS IN SB
DGCA/HS 748/36	INSPECTION OF REPAIRED NOSE UNDER CARRIAGE AXLES FOR FATIGUE CRACKS AND DIMENSIONAL CHECKS.	DOWTY ROTOL SB NO. 32-56E	AS IN SB	AS IN SB
DGCA/HS 748/37	INTRODUCTION OF INCREASED AUTHOFEATHER INHIBIT R.P.M. FROM 11500-12800 R.P.M.	HS 748 SB NO. 76/14 REV.2 (MOD NO. 3741)	31/7/71	AS IN SB
DGCA/HS 748/38	INTRODUCTION OF A NEW CIRCLOP PART NO.200143647	DOWTY ROTOL SB NO. 32-15 (MOD. NO. 97230)	31/12/71	AS IN SB
DGCA/HS 748/39	COPERPLATING OF THE INNER AND OUTER DIAMETERS OF THE BUSH AND THEN CADMIUM PLATING ALL OVER AXLE NUT TORQUE 275/300 16.	DOWTY ROTOL SB NO.32-43E (MOD. NO. C AC 6853)	31-12-71	AS IN SB
DGCA/HS 748/40	INTRODUCTION OF FUSE PROTECTION FOR CABLES IN THE AC FAN CONTROL CIRCUIT.	HS 748 SB NO. 21/83 (MOD NO. 4048)	AS IN SB	AS IN SB
DGCA/HS 748/41	DELETION OF SUPPRESSION DIODES ACROSS THE OPERATING COILS OF RELAYS 429 AND 430 IN THE PROPELLER WORKING HORN CIRCUIT.	HS 748 SB NO. 61/17 (MOD. 4078)	AS IN SB	AS IN SB
DGCA/HS 748/42	PITOT PRESSURE PIPE FROM THE STARBOARD PITOT HEAD TO THE PORT CENTRE INSTRUMENT PANEL - INSPECTION FOR DAMAGE.	HS 748 SB NO. 34/57	AS IN SB	AS IN SB
DGCA/HS 748/43	AUTO FEATHER INHIBITING MICROSWITH OPERATING LEVERS, THROTTLE AND HIGH PRESSURE COCK CONTROLS ON THE ENGINE SUBFRAME - INSPECTION FOR CRACKS.	FAA AD NO. 86-14-09 AND HS 748 SB NO. 76/15 REV. 3	AS IN AD AND SB	AS IN AD AND SB
DGCA/HS 748/44	INTRODUCTION OF TWO NEW DOWELS PART NO. 200143.630 FOR SAFETY LOCKING OF THE NOSE UNDER CARRIAGE AXLE NUT.	DOWTY ROTOL SB. NO. 32/4 (MOD. 97269)	FORTHWITH	AS IN SB
DGCA/HS 748/45	INSPECTION OF CHETTON H.F. ANTENNA AERIALS.	HS 748 SB NO. 23/37	AS IN SB	AS IN SB
DGCA/HS 748/46	CANCELLED VIDE LETTER 9-433/84 AI(2) DT. 15/05/84 IN VIEW OF DGCA/HS748/120			AS
DGCA/HS 748/47	RUDDER TRIM CONTROL SCREW JACK INTRODUCTION OF AN INTERNAL STOP IN LIEU OF EXTERNAL STOP	HS 748 SB NO. 27/61 (MOD NO.4341)	31/7/73	AS IN SB
DGCA/HS 748/48	RUDDER AND REDDUR TRIM CIRCUIT	HS 748 SB NO. 27/54	AS IN SB	APPLICABLE TO SERIES 2A AIRCRAFT FITTED

				WITH R.R. DART MK. 532-2L ENGINES.
DGCA/HS 748/49	MAIN REDDUR CENTRE HINGE BOLT, FOULING RUDDER TRIM TAB OPERATING LEVER AVON.	HS 748 ALERT SB NO. A 27/62	AS IN SB	AS IN SB
DGCA/HS 748/50	EMERGENCY POWER SUPPLY FOR ELECTRICALLY OPERATED GYRO HORIZEN.	HS 748 SB NO. 24/60 REV.4 (MOD NO. 4630)	01/05/74	AS IN SB
DGCA/HS 748/51	EMERGENGE POWER SUPPLY FOR ELECTRICALLY OPERATED GYRO HORIZEN	HS 748 SB NO. 24/61 REV.5 (MOD 4631)	01/05/74	AS IN SB
DGCA/HS 748/52	LANDING GEAR - NOSE LEG- INTRODUCTION OF BAULKING DEVICE	HS 748 SB NO. 32/45	AS IN SB	AS IN SB
DGCA/HS 748/53	STABILIZER-INTRODUCTION OF STRUCTURAL IMPROVEMENTS TO ELEVATOR HINGE RIBS STN.126 AND 187.0.	HS 748 MOD NO. 4872	31/03/74	AS IN MOD BULETIN
DGCA/HS 748/54	WINGS - INTRODUCTION OF STRUCTURAL IMPROVEMENTS TO AILERON HINGE RIBS 440.366 & 495 098.	HS 748 MOD NO. 4873	31-03-74	AS IN MOD BULETIN
DGCA/HS 748/55	WINGS-INTRODUCTION OF STRUCTURAL IMPROVEMENTS TO AILERON.	HS 748 MOD NO. 4874	31-03-74	AS IN MOD BULLETIN
DGCA/HS 748/56	WINGS-INTRODUCTION OF STRUCTURAL IMPROVEMENTS TO WING TIP	HS 748 MOD NO. 4875	31-03-74	AS IN MOD BULLETIN
DGCA/HS 748/57	INTRODUCTION OF R.R. DART 531 U ENGINES INCLUDING COMPLEMENTRY MODS.	HS MOD NOS 4579, 3826, 4341 AND 4027	30-04-74	DART 531 ENGINE
DGCA/HS 748/58	AIRPLANE MODIFICATION FOR NACELLE COOLING	HS 748 SB.NO. 75/2,75/3,75/4, AND 75/5	30/04/74	AS IN SB
DGCA/HS 748/59	TO PROVIDE ELECTRICAL BACK UP SYSTEM TO PROP. FEATHERING MANUAL SYSTEM.	HS 748 ALERT SB NO. 61/18 REV. 2, (MOD. 4609)	AS IN SB	AS IN SB
DGCA/HS 748/60	INTRODUCTION OF STRENGTHENED BEAM OF MAIN UNDER CARRIAGE.	DOWTY ROTOL SB. NO. 32-49 E REV.3	AS IN SB	AS IN SB
DGCA/HS 748/61	INSPECTION OF PROPELLER HUBS FOR CRACKS IN THE FRONT WALL	DOWTY ROTOL SB NO. 61-828 REV.2	AS IN SB	AS IN SB
DGCA/HS 748/62	RETIREMENT LIVES OF ENGINE SUB-FRAME.	HS 748 SB NO. 54/23 REV. 1	AS IN SB	AS IN SB
DGCA/HS 748/63	CRACKS IN RADIUSED REGION OF TYRE BEAD SEAT OF THE WHEELS TO BE CHECKED BY ULTRASONIC OR EDDY CURRENT METHOD AS PER DUNLOP OVERHAUL MANUAL DM 1258 CH 32-21-6 PARA 3 A&B	DGCA LETTER NO. 9-433/72-AI(2) DATED 12 -11-74	AT EACH TYRE CHANGE AT EACH WHEEL ASSEMBLY O/H	ALL HS 748 AIRCRAFT
DGCA/HS 748/64	CRACKS IN HOLES OF AXLE HOUSING RETAINING BOLT IN INNER CYLINDER P/N 2020833 TO BE CHECKED BY MAGNAFLUX METHOD	DGCA LETTER NO. 9-433/72-AI(2) DATED 25/11/74	NOT LATER THAN NEXT CH.1 AND THEREAFTER EVERY 650 HOURS UNTIL (b) IS ACCOMPLISHED. (B) MODIFY ASSEMBLY DURING NEXT OVERHAUL FOR UNITS WHICH ACHIEVED 8000 LDGS AS PER ROTOL MOD NO AC 7297 & TO BE REIDENTIFIED AS PER DOWTY ROTOL SB 32-59E.	ALL HS 748 AIRCRAFT.

DGCA/HS 748/65	FAILURE OF INSULATION OF ELECTRICAL CABLES RUNNING FROM NACELLED ALONG LEADING EDGE TO BE USUALLY INSPECTED FOR DETERIORATION DUE TO HEAT/OIL SOAKING/CHAFING ETC.	DGCA LETTER NO. 9-433/72-AI(2) DATED 25/11/74	(A) NOT LATER THAN NEXT CH.1 INSPECTION AND THEREAFTER AT INTERVALS OF 1500 HOURS (DURING CH-11 INSPECTION).(B) ON AIRCRAFT WITH 1500 HOURS AND THERAFTER EVERY 15000 HOURS REPLACE ELECTRICAL CABLES RUNNING INSIDE JET PIPE COMPARTMENT WITH NEW CABLES.	ALL HS 748 AIRCRAFT
DGCA/HS 748/66	CANCELLED ON 14/05/76			
DGCA/HS 748/67	INSPECTION OF AXLES-LANDING GEAR NOSE UNDERCARRIAGE	DOWTY ROTOL SB NO. 32-75E REV.3	AS IN SB	AS IN SB
DGCA/HS 748/68	LANDING GEAR-INSPECTION AND RECTIFICATION OF TOGGLE LINKS PART NO. UC 3013183 & UC 3013184 FITTED ON NOSE UNDERCARRIAGE.	HAL SB NO.HAL/32/1	AS IN SB	AS IN SB WITH THE COMPLIANCE OF DGCA/HS 748/77, THIS STANDS DELETED.
DGCA/HS 748/69	LANDING GEAR-MAIN UNDERCARRIAGE JACK-INSPECTION OF EYE END FITTING ON HS 748 AIRCRAFT	DOWTY ROTOL SB NO. 32-78 E REV.3	AS IN SB	AS IN SB
DGCA/HS 748/70	REPLACEMENT OF THE D.C.VOLTAGE REGULATOR DIODES 6 PT NO. N 147074/2 AND MR PT. NO. N 147074/7 WITH IMPROVED DIODES PT. NO. 202429/7.	DGCA LETTER NO. 9-433/72-AI(2) DATED 20-03-75	WITH IMMEDIATE EFFECT	APPLICABLE ALL HS 748 SERIES 2 AIRCRAFT
DGCA/HS 748/71	INSPECTION OF MAIN HYD. PRESSURE MAINFOLD BLOCK IN STARBOARD NACELLE HYD. BAY.	HAL SB NO. 29/33	AS IN SB	AS IN SB
DGCA/HS 748/72	INSTALLATION OF FOUR IDENTICAL VIBRATION ISOLATOTRS UNDER RACK SUPPORTING MODEL 209 DIGITAL FDR.	FAA AD NO. 75-08-17	AS IN AD	AS IN AD
DGCA/HS 748/73	VENTING OF CLUTCH ASSEMBLY MOTORS OF SEP-2AP	SMITH SB NO.22-873	AS IN SB	AS IN SB
DGCA/HS 748/74	ULTIMATE LIFE OF KNIFE EDGES ASSEMBLED ON HYDRAULIC BRAKE AONTROLS.	DUNLOP SB NO. 29-138 REV.2	AS IN SB	AS IN SB
DGCA/HS 748/75	USE OF RAIN REPELLENT R.R.990 ON THE WIND SCREEN AT AN INTERVAL OF 15 DAYS (DURING MONSOON).	DGCA'S LATTER NO. 4-73/71-AI(1) DT 17-12-75.	EFFECTIVE FORTHWITH	ALL HS 748 AIRCRAFT
DGCA/HS 748/76	FUEL BOOSTER PUMP FAILURE	PLESSY SB NO.PU28-14 DATED 17/11/71 (MOD. 2006 C)	WITH IN 30-12-76	APPLICABLE TO ALL HS 748 AIRCRAFT
DGCA/HS 748/77	MODIFICATION OF STREEING TOGGLES NOSE UNDERCARRIAGE	DOWTY ROTOL SB NO. 32-79 E	WITH IN 30-9-76	ALL HS 748 AIRCRAFT
DGCA/HS 748/78	WING STRUCTURE RADIOGRAPHIC INSPECTION	HAL SB NO. 57/34 REV. 7	FORTHWITH	SERIES 1,2 AND 2A ALL MODELS
DGCA/HS 748/79	INTRODUCTION OF STRENGTHENED CUPWASHER-SUPER CHARGER DRIVE GROUP ACCESSORY GEAR BOXES.	DOWTY ROTOL SB NO.83-484	WITHIN 30-6-77	AS IN SB

DGCA/HS 748/80	CANCELLED VIDE DGCA LETTER 9-433/83-AI(2) VOL. IX DT.3-10-83			
DGCA/HS 748/81	WINGS-NACELLE ATTACHMENT ANGLES -INTRODUCTION OF STRONGER ATTACHMENT ANGLES WITH IMPROVED FASTENING	HS 748 SB NO.57/20	WITHIN 31-3-78	AS IN SB
DGCA/HS 748/82	INTRODUCTION OF A STEEL SPINDLE IN THE AILERON CONTROL QUADRENT ASSEMBLY LOCATED BETWEEN RIB STATIONS 323 AND 332.	HS 748 SB NO.27/75 REV.1	FORTHWITH	AS IN SB
DGCA/HS 748/83	WINGS -STRUCTURE-INSPECTION FROM INBOARD EDGE OF BUTT STRAP AT RIB "O" THROUGH TO RIB "16"	HS 748 SB NO. 57/55 REV. 4	FORTHWITH	AS IN SB
DGCA/HS 748/84	INSPECTION OF JOINT BETWEEN TAILPLANE CENTRE TORSION BOX AND OUTER TAIL PLANES	HS 748 SB NO. 55/19 REV.1	AS IN SB	AS IN SB
DGCA/HS 748/85	INTRODUCTION OF DUPLICATE CONNECTION FROM THE CENTRE BUS BAR TO THE CIRCUIT BREAKER BUS BAR	HS 748 SB NO. 24/89	AS IN SB	AS IN SB
DGCA/HS 748/86	NACELLES -ENGINE SUBFRAME-INSPECTION FOR CORROSION.	HS 748 SB NO. 54/25 REV.2	AS IN SB	AS IN SB
DGCA/HS 748/87	INSPECTION OF MAIN UNDERCARRIAGE JACK ATTACHMENT PIN	DOWTY ROTOL SB NO.32-85 E	AS IN SB	AS IN SB
DGCA/HS 748/88	INSPECTION OF SHUTTLE VALVE RETAINING BOLT IN NOSE UNDERCARRIAGE JACK	DOWTY ROTOL SB NO. 32-91 E REV.1	30-4-79 CH.I INSPECTION WHICH EVER IS EARLIER	ALL HS 748 AIRCRAFT
DGCA/HS 748/89	INSPECTION OF OPERATING MACHANISM OF EMERGENCY EXIT PANEL	HS 748 SB NO.A52/82 REV.1	WITHIN 10 FLIGHTS FROM 8-6-79 AND WHENEVER THE EMERGENCY EXIT IS OPENED	ALL HS 748 AIRCRAFT
DGCA/HS 748/90	CHANGES TO THE PROPELLER CONTROL ELECTRICAL CIRCUIT WIRING INTRODUCED BY MODIFICATION 5142 OR 5445	HS 748 SB NO. 61/30	15-10-79	HS 748 AIRCRAFT INCORPORATING MOD 5142 OR 5445.
DGCA/HS 748/91	INSPECTION OF GUST LOCK LEVER AND GATE PLATE IN CENTRE CONSOLE	HS 748 SB.NO. 27/76 REV.2	AS IN AD	ALL HS 748 AIRCRAFT
DGCA/HS 748/92	INSPECTION OF INBOARD MAIN UNDERCARRIAGE PIVOT BRACKET PART NO.15 & 16F 11365 FOR CRACKS	F.A.A. A.D.NO.88-06-01 AND HS 748 SB NO.57/59 REV.1	AS IN AD & SB	AS IN AD & SB
DGCA/HS 748/93	DIMENSIONAL CHECK ON BORE OF BUYONET CONNECTION OF FIXED SOCKET AND FLOW SELECTOR.	NORMALAIR GARRETT ALERT SB NO. 35-123 REV.1	WITHIN 50 FLYING HOURS FROM 15-1-80	AS IN SB
DGCA/HS 748/94	INTRODUCTION OF REVISED AIRSPEED LIMITATIONS LABEL.	HS 748 ALERT SB NO. 11/2	1-3-80	HS 748 AIRCRAFT WITH MOD 3177 OR 4557 INCORPORATED.
DGCA/HS 748/95	INSPECTION AND MODIFICATION OF SEALED RELAYS 34 AND 35 IN PROPELLER CONTROL UNIT.	HS 748 ALERT SB NO.61/31	1-3-80	ALL HS 748 AIRCRAFT
DGCA/HS 748/96	INSPECTION OF RIB-STRINGER BRACKET FASTENERS WING BOTTOM SURFACE AT RIB 224.366 AND AT STRINGER 4 AND 6 AT ALL RIBS ON EACH SIDE OF WING ACCESS PANELS W3 TO W12 EXCEPT W10	HS 748 SB NO. 57/62	AS IN SB	AS IN SB
DGCA/HS 748/97	INSPECTION OF RIB-STRINGER BRACKET FASTENERS, WING BOTTOM SURFACE RIB 16/071 AND STRINGERS NUMBER 9,10,11 AND 12	HS 748 SB NO. 57/63	AS IN SB	AS IN SB
DGCA/HS 748/98	INSPECTION AND RECTIFICATION OF AILERON HINGE CARRIER ASSEMBLY WING STN..368,366,440,366 AND 495,098.	H.A.L. SB NO.HAL-K-57/1 AND HS 748 SB NO.57/67	AS IN SB AND REPEAT INSPECTION AT EVERY CH. II SCHEDULE	ALL HS 748 AIRCRAFT

DGCA/HS 748/99	PRE FLIGHT AND MAINTENANCE CHECK OF DOORS FOR LOCKING AND SECURITY	HS 748 SB NO.A52/90 REV.1	AS IN SB	ALL HS 748 AIRCRAFT
DGCA/HS 748/100	INSPECTION OF BRAKE UNITS FOR UNAPPROVED PARTS.	DUNLOP SB NO.32-A930	AS IN SB	ALL HS 748 AIRCRAFT
DGCA/HS 748/101	INTRODUCTUION OF PLATE SEPARATORS BETWEEN PART H.P. COCK CABLES AND CONTROL LOCK CABLES UNDER CABIN BETWEEN STN. 126F AND 162F	HS 748 SB NO.27/81	1-12-81	ALL HS 748 AIRCRAFT
DGCA/HS 748/102	INSPECTION OF NOSE LANDING GEAR RETRACTION JACK SUPPORT BRACKETS	CAA. AD NO.013-11-86, FAA. AD NO. 87-25-13, HAL SB NO.HAL-K-53/1 DATED 23-9-81 AND BRITISH AEROSPACE SB NO.A53/53 REV.1	AS IN AD AND SB	AS IN AD AND SB
DGCA/HS 748/103	INTRODUCTION OF A MODIFIED INNER HANDLE CAM AND WEAR INDICATOR PLATE ON THE BAGGAGE DOOR.	HS 748 SB NO. 52/94	AS IN SB	AS IN SB
DGCA/HS 748/104	INTRODUCTION OF A MODIFIED INNER HANDLE CAM INCORPORATEING A WEAR INDICATOR PLATE ON PASSENGER AND AIR CREW/FREIGHT DOORS.	HS 748 SB NO. 52/95	AS IN SB	AS IN SB
DGCA/HS 748/105	INTRODUCTION OF IMPROVED DOOR APERTURE MICRO SWITCH MOUNTINGS AND STRIKERS ON BAGGAGE PASSENGER AND AIR CREW/FREIGHT DOORS	HS748 SB NO. 52/96	AS IN SB	AS IN SB
DGCA/HS 748/106	INTRODUCTION OF A DECAL WARNING LABELS ON THE INTERIOR TRIM OF PASSENGER BAGGAGE AND CREW/FREIGHT DOORS.	HS 748 SB NO.52/97	AS IN SB	AS IN SB
DGCA/HS 748/107	INTRODUCTION OF IMPROVED DOOR APERTURE MICRO SWITCH MOUNTINGS AND STRIKERS ON BAGGAGE AND CREW/FREIGHT DOORS ON LARGE FREIGHT DOOR AIRCRAFT	HS 748 SB NO. 52/99	AS IN SB	AS IN SB
DGCA/HS 748/108	INTRODUCTION OF DECAL WARNING LABELS ON THE INTERIOR TRIM OF THE FORWARD SLIDING PORTION OF THE LARGE FREIGHT DOORS.	HS 748 SB NO.52/100	AS IN SB	AS IN SB
DGCA/HS 748/109	INSPECTION OF FRONT AND REAR SPAR FORMER UNDER THE FLOOR AND FUSELAGE UNDER FLOOR STRUCTURE	HLA. SB NO.HAL-K-53/2	AS IN SB	AS IN SB
DGCA/HS 748/110	INSPECTION OF MAIN LANDING GEAR RETRACTION JACK BRACKET ATTACHMENT BOLTS OF 3/8" DIA.	HAL SB NO.HAL-K-57/3	AS IN SB	AS IN SB
DGCA/HS 748/111	INTRODUCTION OF NEW RUDDER CONTROL LEVER, ELEVATOR LOCK LEVER AND AILERON LOCK LEVER	HAL. SB. NO.27/88 REV.2	AS IN SB	AS IN SB
DGCA/HS 748/112	INTRODUCTION OF A STOP TO THE CABLE GURD ASSEMBLY ON THE AILERON TENSION REGULATOR.	HS 748 SB NO. 27/92	PARA 2A OF SB WITHIN 7 DAYS FROM THE RECEIPT OF SIGNAL AND REST AS IN SB	AS IN SB
DGCA/HS 748/113	INTRODUCTION OF A LIFE AND AN INSPECTION OF BOTH CREW/FREIGHT DOOR LOCKING MECHANISM SWIVEL LEVERS	HS 748 SB NO.52/101 REV 1	AS IN SB	AS IN SB
DGCA/HS 748/114	INTRODUCTION OF A MINIMUM STANDARD DOOR UNSAFE AUDIBLE WARNING SYSTEM	HS 748 SB NO.52/109	AS IN SB	AS IN SB
DGCA/HS 748/115	INSPECTION FOR ELECTRICAL INTEGRITY OF SILL AND SECONDARY LOCKING MECHANISM MICRO-SWITCHES ON ALL DOORS	HS 748 SB NO. 52/106	AS IN SB	AS IN SB
DGCA/HS 748/116	REAR PRESSURE BULKHEAD AND FIN ATTACHMENT FITTING INSPECTION	HS 748 SB NO. 53/49 REV.1	AS IN SB	AS IN SB
DGCA/HS 748/117	INSPECTION OF BOTH OF ELEVATOR CONNECTING ROD BELL CRANK LEVERS.	HS 748 SB NO. 27/93	AS IN SB	AS IN SB
DGCA/HS 748/118	INSPECTION OF WING STRUCTURE AT RIB 134.366 AND ADJACENT AREAS (PORT	HS 748 SB NO. 57/75 REV.2	AS IN SB	AS IN SB

	AND STARBOARD)			
DGCA/HS 748/119	INSPECTION TO ENSURE CORRECT INSTALLATION OF INTERMEDIATE CROSS SHAFT IN THE CENTRE CONSOLE	HS 748 MANDATORY SB NO.27/99	AS IN SB	AS IN SB
DGCA/HS 748/120	INSPECTION OF DUNLOP HYDRAULIC ACCUMULATOR P/N AC.14040	CAA AD NOS 008-02-86,001-03-84 AND DUNLOP SB NO. 29/175 AND 29/42	AS IN AD AND SB	AS IN AD AND SB
DGCA/HS 748/121	OVER WING ESCAPE HATCH-INTRODUCTION OF A MECHANICAL LOCKED/UNLOCKED DIRECT VISION INDICATOR AND WORKING DECAL.	CAA AD NOS 011-09-85,008-07-84 AND BR. AEROSPACE SB NOS. 52/127 & 52/115	AS IN AD AND SB	AS IN AD AND SB
DGCA/HS 748/122	INSPECTION OF STRUCTURALLY SIGNIFICANT ITEMS ON HS 748 AIRCRAFT	BR. AEROSPACE HS 748 SUPPLEMENTARY STRUCTURAL INSPECTION DOCUMENT AND BR. AEROSPACE SB NO.12/11 REV.1	AS IN DOCUMENT AND SB	AS IN DOCUMENT AND SB
DGCA/HS 748/123	WINGS-REMOVAL OF CENTRAL REINFORCEING STRAPS FITTED BY SB NO.75/31 AND 57/33 FOR INSPECTION OF CRACKS	FAA AD NO. 88-03-02, CAA AD NO. 002-08-84 AND BR. AEROSPACE SB NO. 57/81 REV.2	AS IN SB	AS IN SB
DGCA/HS 748/124	WINGS-REMOVAL OF CENTRAL REINFORCING STRAPS FITTED BY SB NO. 57/32 FOR INSPECTION OF CRACKAS	FAA AD NO. 88-03-02, CAA AD NO.003-08-84 AND BR. AEROSPACE SB NO. 57/82 REV.2	AS IN SB	AS IN SB
DGCA/HS 748/125	INSPECTION OF SPIGOT MOUNTING BRACKETS ON FORMER 126A AND INTRODUCTION OF INCREASED DIAMETER BOLTS AT THE CENTRE SPIGOT MOUNTING BRACKET.	BR. AEROSPACE SB NO.52/84	AS IN SB	AS IN SB
DGCA/HS 748/126	CANCELLED VIDE LETTER NO.9-433/84-AI(2) DATED 13/08/85			
DGCA/HS 748/127	INSPECTION OF THE THREE RETAINING PLATE ASSEMBLIES SECURING THE JET PIPE INSIDE THE JET PIPE MANIFOLD	FAA AD NO.87-25-06 CAA AD NO. 011-04-85 AND HS 748 MANDATORY SB NO. 78/9 REV.1	AS IN AD AND SB	AS IN AD AND SB
DGCA/HS 748/128	INSPECTION OF THE WIND SCREEN WIPER ACTUATING ARM IN THE ATTACHMENT ARM	DUNLOP SB NO.30/92	AS IN SB	AS IN SB
DGCA/HS 748/129	FITMENT OF BATTERY SUPPLIED C.Bs AND RELAYS IN THE PORT AND STARBOARD DISTRIBUTION PANEL.	HS 748 SB NO. 24/104	AS IN SB	AS IN SB
DGCA/HS 748/130	NAV-TO RE- ROUTE ELECTRICAL WIRING TO THE STAND BY HORIZON TO ENABLE BATTERY POWER SUPPLY TO BE INDEPENDENT OF GYRO ISOLATION.	CAA AD NO.010-04-85 AND BR. AEROSPACE SB. NO.34/116 REV.2	AS IN AD AND SB	AS IN AD AND SB
DGCA/HS 748/131	NAV-INSPECTION OF STANDBY HORIZON NORMAL/EMERGENCY SWITCH WITH ASSOCIATED BATTERY BUS BAR POWER SUPPLY	CAA AD NO.009-04-85 AND BR. AEROSPACE SB NO.3/115 REV.3	AS IN AD ANS SB	AS IN AD AND SB
DGCA/HS 748/132	FLIGHT CONTROLS -RUDDER GUST LOCK -INTRODUCTION OF ORIENTATION OF	FAA AD NO.88-05-03 AND	AS IN SB	AS IN SB

	THE SPRING STRUT RUDDER LOCK CONTROL TO PREVENT THE POSSIBILITY OF A FOUL BETWEEN THE STRUT AND THE LOWER RUDDER HINGE BAR	BR. AEROSPACE SB NO. 27/109		
DGCA/HS 748/133	TO REPLACE FLOOR LOAD LIMITATIONS LABELS P/N 679SS6065 WITH REVISED LABELS P/N 55SS6222.	CAA AD NO.002-03-86 AND BR. AEROSPACE SB NO. 11/6	AS IN AD AND SB	AS IN AD AND SB
DGCA/HS 748/134	MODIFICATION OF EMERGENCY ELECTRICAL SYSTEM TO PREVENT ACCIDENTAL DISARMING	FAA AD 86-09-04 AND BR. AEROSPACE SB NO.33/29	AS IN AD AND SB	AS IN AD AND SB
DGCA/HS 748/135	TO ENSURE THE CORRECT OPERATION OF THE LARGE FREIGHT DOOR LOCKING MECHANISM AND INDICATION	FAA AD 87-22-05, CAA AD NOS. 007-02-87,008-02-87 AND BR. AEROSPACE SB NO. 52/129 REV.1 AND 11/7.	AS IN AD AND SB	AS IN AD AND SB
DGCA/HS 748/136	NACELLES AND PYLONS-INTRODUCTION OF AN INSPECTION OF THE ENGINE SUBFRAME WING ATTACHMENT ASSEMBLY FOR SIGNS OF ABNORMAL MOVEMENT AND WEAR.	FAA AD NO.87-25-07 CAA AD NO 026-11-86 AND BR. AEROSPACE SB NO. 54/29	AS IN AD AND SB	AS IN AD AND SB
DGCA/HS 748/137	FLIGHT CONTROLS -INSPECTION OF WALKER AND SCHAFIELD BEARING RETANING RINGS	FAA AD NO. 87-25-11 CAA AD NO. 006-03-87 AND BR. AEROSPACE SB NO. 27/110	AS IN AD AND SB	AS IN AD AND SB
SGCA/HS 748/138	INSPECTION AND REPAIR OF THE ELEVATOR OUBOARD HINGE STRUCTURE	B.Ae. SB NO. 55/24 REV.1	AS IN SB	AS IN SB
DGCA/HS 748/139	ELECTRICAL POWER -INTRODUCTION OF UNDER VOLTAGE WARNING INDICATOR ON PILOTS CONTROL PANEL	CAA AD 026-05-87 AND Bae SB NO. 24/97 REV.6	AS IN AD AND SB	AS IN AD AND SB
DGCA/HS 748/140	ELECTRICAL POWER-INTRODUCTION OF SMITHS 115/26 VOLTS STEP DOWN TRANSPFORMER P/N 715/SUE/1 IN LIEU OF P/N213 MV1.	CAA AD NO. 027-05-87 AND BR. AEROSPACE SB NO.24/121	AS IN AD AND SB	AS IN AD AND SB
DGCA/HS 748/141	CHECK FOR CORRECT INSTALLATION OF CHAIN AND PIN ASSEMBLY ON PORT AND STARBOARD MAIN UNDER CARRIAGE MECHNISM	CAA AD NO. 010-08-88 AND B.Ae. ALERT SB NO.A32-80	AS IN AD AND SB	AS IN AD AND SB
DGCA/HS 748/142	INSPECTION OF TAIL PLANE CENTRE SECTION TORSION BOX FOR DAMAGE	CAA AD NO. 008-08-88 AND Bae ALERT SB NO. A55/25	AS IN AD AND SB	AS IN AD AND SB
DGCA/HS 748/143	INSPECTION FOR CORRECT FITMENT OF AYE BOLT TO ENGNE SUBFRAME ASSEMBLY	CAA AD NO. 009-08-88 AND B. Ae ALERT SB NO. 54/31	AS IN AD AND SB	AS IN AD AND SB
DGCA/ HS 748/144	INSPECTION OF LANDING GEAR SELECTOR LEVER ASSEMBLY	CAA AD NO. 028-01-89 AND B Ae ALERT SB NO. A32-81	AS IN AD AND SB	AS IN AD AND SB
DGCA/HS 748/145	INSPECTION AND REPLACEMENT OF PRE AND POST MOD. 684 NLG JACK SUPPORT BEAM P/N 48D11498.	B. Ae MANDATORY SB NO. 53/55	AS IN SB	AS IN SB
DGCA/HS 748/146	INTRODUCTION OF ELEVATOR LIMIT STOPS WITH IMPROVED CAP	B. Ae MANDATORY SB NO. 27/101 REV. 1	AS IN SB	AS IN SB
DGCA/HS 748/147	INTRODUCTION OF IMPROVEMENTS TO THE FLAP POSITION CONTROL SYSTEM	CAA AD NO. 012-02-89 & B. Ae MANDATORY SB NO. 27/112 REV.2	AS IN AD AND SB	AS IN AD AND SB
DGCA/HS 748/148	DOORS-OVERWING ESCAPE HATCH INTRODUCTION OF REVISION TO	CAA AD NO. 011-07-89	AS IN AD AND SB	AS IN AD AND SB

	OPERATING LEVER/CAM SETTING	AND Br.Ae SB NO. 52/130		
DGCA/HS 748/149	INSPECTION OF NOSE UNDERCARRIAGE FOR CRACKS	CAA AD 007-08-90	AS IN AD	AS IN AD
DGCA/HS 748/150	INTRODUCTION OF LIFELIMIT TO MAIN UNDERCARRIAGE RADIUS ROD TUBES	CAA AD 009-02-93 AND DOWTY AEROSPACE LANDING GEAR SB 32-104E	AS IN AD AND SB	AS ION AD AND SB
DGCA/HS 748/151	INTRODUCTION OF LIFE LIMIT TO MAIN UNDERCARRIAGE CROSS BEAM AND RADIUS ROD SUBASSMEBLY.	CAA NO. 009-02-93 AND DOWTY AEROSPACE LANDING GEAR SB 32-104E	AS IN AD AND SB	AS IN AD AND SB
DGCA/HS 748/152	INTRODUCTION OF LIFE LIMIT TO MAIN UNDERCARRIAGE ATTACHMENT PIN	CAA AD 009-02-93 AND DOWTY AEROSPACE LANDING GEAR 32-104E	AS IN AD AND SB	AS IN AD AND SB
DGCA/HS 748/153	INTRODUCTION OF LIFE LIMIT TO MAIN UNDERCARRIAGE CROSSBEAM ATTACHMENT PIN.	CAA AD 009-02-93 AND DOWTY AEROSPACE LANDING GEAR SB 32-104E	AS IN AD AND SB	AS IN AD AND SB
DGCA/HS 748/154	REVISION OF MODIFICATION TO MAIN UNDERCARRIAGE CROSSBEAM ATTACHMENT PIN.	CAA AD 012-08-90	AS IN AD	AS IN AD
DGCA/HS 748/155	LIFING OF MAIN UNDERCARRIAGE COMPONENT UNITS AND DETAILS	CAA AD 009-02-93 AND DOWTY AEROSPACE LANDING GEAR SB 32-104E	AS IN AD AND SB	AS IN AD AND SB
DGCA/HS 748/156	LANDING GEAR NOSE LANDING GEAR RETRACTION JACK SECURITY OF RING NUT LOCKING	CAA AD 016-10-90	AS IN AD	AS IN AD
DGCA/HS 748/157	TO INTRODUCE A ONCE ONLY INSPECTION OF LANDING GEAR NORMAL SELECTION LEVER ASSEMBLY AND FUNCTIONAL CHECK OF THE LANDING GEAR EMERGENCY RELEASE SYSTEM	BAe SB 32/83 & CAA AD 009-12-90	AS IN AD AND SB	AS IN AD AND SB
DGCA/HS 748/158	INTRODUCTION OF ONCE ONLY INSPECTION OF FLAP TRACKS TO ENSURE THEY HAVE NOT BEEN REPAIRED INACCORDANCE WITH NON BRITISH AEROSPACE REPAIR SCHEMES	BAe SB 57/86 & CAA AD 022-11-90	AS IN AD AND SB	AS IN AD AND SB
DGCA/HS 748/159	INSPECTION OF THE NOSE LANDING GEAR RETRACTION BRACKET ATTACHMENT ASSEMBLY AND REPAIR/REPLACEMENT AS NECESSARY	CAA AD 001-02-91 AND BAe SB NO. 53/57 REV.1	AS IN AD AND SB	AS IN AD AND SB
DGCA/HS 748/160	WINGS TO INTRODUCE A "ONE-OF" INSPECTION OF WING ROOT JOINT STRAPS (BOTTOM SURFACE) TO CHECK FOR INCORRECT FASTENER TYPES.	CAA AD 004-04-91	AS IN AD	AS IN AD
DGCA/HS 748/161	DOORS INTRODUCTION OF RETURN SPRING ON DOOR OPEN RETAINING HOOK	CAA AD 017-04-91	AS IN AD	AS IN AD
DGCA/HS 748/162	TO INTRODUCE A ONCE ONLY INSPECTION OF THE AILERON SPRING LOADING LEVER HALF CLIP ASSEMBLY.	CAA AD 018-04-91	AS IN AD	AS IN AD
DGCA/HS 748/163	INTRODUCTION OF REVISED STOP ON RUDDER SPRING TAB.	CAA AD 015-11-88 AND BAe SB 27/114 LATEST REVISION	BEFORE 31ST DEC. 1991	AS IN AD AND SB
DGCA/HS 748/164	IMPROVEMENT TO HYDRAULIC SYSTEM HIGH PRESSURE FILTER	CAA AD 010-12-93 AND JETSTREAM SB 29/45 R1	AS IN AD AND SB	AS IN AD AND SB
DGCA/HS 748/165	MODIFIED PRESSURE SWITCHES FOR IMPROVED LOW LEVER BRAKE WARNING	CAA AD 011-12-93 AND JETSTREAM CAA MAN SB 748-32-94	AS IN AD AND SB	AS IN AD AND SB
DGCA/HS 748/166	NOSE LANDING GEAR-INSPECTION/RECTIFICATION OF RETRACTION JACK MOUNTING BRACKET BEARING CAP FASTENERS	CAA AD 007-05-94 HS 748 SB (CAA) MANDATORY HS	AS IN AD AND SB	AS IN AD AND SB

		748 -53-59-INSP.		
DGCA/HS 748/167	FLIGHT CONTROL-INTRODUCTION OF AILERON CABLE SUPPORT BLOCK UNDER THE CREW COMPARTMENT	CAA AD 008-05-94	AS IN AD	AS IN AD
DGCA/HS 748/168	FLIGHT CONTROL-INTRODUCTION OF A MODIFIED AILERON CABLE PULLEY GUARD AT STATION 314-366 AND RUBBING STRIPS AT RIBS 34.071, 43.071 AND 52-071 ON THE PORT AND RIBS 251366 AND 260.360 ON THE STARBOARD SIDE	CAA AD 009-05-94	AS IN AD	AS IN AD
DGCA/HS 748/169	ENGINE MOUNT STRUCTURE TO FRAME SOCKET- EXAMINATION OF INSPECTION HOLE	CAA AD 002-09-99 &SB HS748-71-33	AS IN AD	AS IN AD
DGCA/HS 748/170	REPETITIVE REPLACEMENT OF SSI ON NLG & MLG WITH SERVICEABLE SSI'S	FAA AD 94-23-08 & DOWTY SB 32-104 E	AS IN AD & SB	AS IN AD & SB
DGCA/HS 748/171	TO MINIMISE THE POTENTIAL HAZARDS ASSOCIATED WITH OPERATING THE AIRPLANE IN SEVERE ICING CONDITIONS.	FAA AD 96-09-20	AS IN AD	AS IN AD
DGCA/HS 748/172	FLIGHT CONTROLS- CONTROL SYSTEM GUEST LOCKS	CAA AD 008-12-96	AS IN AD	AS IN AD
DGCA/HS 748/173	FUEL BURNER INSPECTION	ALERT SB DA 73-A87	AS IN ASB	AS IN ASB
DGCA/HS 748/174	FUEL DISTRIBUTION- CHAFE DAMAGE TO A CROSSFEED DRAIN PIPE	CAA AD 002-09-2002	AS IN AD	AS IN AD
DGCA/HS 748/175	FUEL DISTRIBUTION- INSPECTION OF ELECTRICAL CABLE LOOM IN PORT & STARBOARD WING DRY BAYS	CAA AD 003-02-2003	AS IN AD	AS IN AD
DGCA/HS 748/176	ELECTRICAL POWER- RELOCATION OF BATTERY EARTH PORTS	CAA AD 006-01-2003	AS IN AD	AS IN AD
DGCA/HS 748/177	INSTALLATION OF A BAULKING ACTUATOR ON THE ELEVATOR GUST LOCK	CAA AD G 2004-0002	AS IN AD	AS IN AD
DGCA/HS 748/178	TIME LIMITS / MAINTENANCE CHECKS --- FUEL TANK SAFETY AIRWORTHINESS LIMITATIONS --- IMPLEMENTATION	EASA AD 2008 - 0125	AS IN AD	AS IN AD
DGCA/HS 748/179	FLIGHT CONTROLS --- AILERON AND RUDDER TAB HINGE PINS --- INSPECTION	EASA AD 2010 - 0035	AS IN AD	AS IN AD
DGCA/HS 748/180	FLIGHT CONTROLS --- CONTROL COLUMN LOWER AILERON CHAIN DRIVES --- MODIFICATION	EASA AD 2010 - 0249	AS IN AD	AS IN AD