

DGCA NO	SUBJECT	REFERENCE	COMPLIANCE	APPLICABILITY
DGCA / PIPER PA-12/1	LOOSENING OF THE CAP SCREWS ATTACHING THE SCOOP TO THE CURBURATOR	FAA AD 46-36-02 SB NO.90	AS IN AD & SB	AS IN AD & SB
DGCA / PIPER PA-12/2	TO PREVENT POSSIBLE FAILURE OF THE TAIL PIPE AND CRACKING OF THE MUFFLER	FAA AD 46-36-03 SB NO.92	AS IN AD & SB	AS IN AD & SB
DGCA / PIPER PA-12/3	TO PREVENT POSSIBLE FAILURE OF THE FUEL STRAINER BOWL	FAA AD 46-37-01 SB NO.89	AS IN AD & SB	AS IN AD & SB
DGCA / PIPER PA-12/4	REINFORCEMENT OF THE LANDING GEAR UPPER END TIE STRAP	FAA AD 47-22-03 SB NO.93	AS IN AD & SB	AS IN AD & SB
DGCA / PIPER PA-12/5	REINFORCEMENT OF THE A/C UPPER END TIE STRAP WITH A 4130 STEEL PLATE	FAA AD 47-47-01 SB NO.97	AS IN AD & SB	AS IN AD & SB
DGCA / PIPER PA-12/6	TO ELIMINATE SHORT CIRCUIT OCCURING BETWEEN THE BATTERY TERMINAL BASES AND BATTERY BOX	FAA AD 47-47-02 SB NO.98	AS IN AD & SB	AS IN AD & SB
DGCA / PIPER PA-12/7	TO PREVENT POSSIBLE MALFUNCTIONING OF THE STARTER SOLENOID	FAA AD 47-47-04 SB NO.102	AS IN AD & SB	AS IN AD & SB
DGCA / PIPER PA-12/8	INSPECT FOR INTERFERENCE BETWEEN THE NOSE COWL AND STARTER RING GEAR CASTING	FAA AD 48-01-02 SB NO.100	AS IN AD & SB	AS IN AD & SB
DGCA / PIPER PA-12/9	TO PREVENT ARCING BETWEEN THE FUSE CLIP AND THE WIRE ATTACHMENT PLATE ON THE FUSE BLOCK	FAA AD 48-13-04 SB NO.105	AS IN AD & SB	AS IN AD & SB
DGCA / PIPER PA-12/10	TO ELIMINATE BATTERY SHORT CIRCUITS CAUSED BY DEFECTIVE BATTERY HOLDDOWN BRACKETS	FAA AD 48-13-03 SB NO.105	AS IN AD & SB	AS IN AD & SB
DGCA / PIPER PA-12/11	TO PREVENT POSSIBLE FUEL LEAKAGE AT THE ELBOW FITTING CONNECTION	FAA AD 48-14-01SB NO.104	AS IN AD & SB	AS IN AD & SB
DGCA / PIPER PA-12/12	INSPECTION OF ELEVATOR CONNECTOR TUBE FITTING	FAA AD 49-14-01 SB NO.111	AS IN AD & SB	AS IN AD & SB
DGCA / PIPER PA-12/13	INSPECTION OF AILERON BELL CRANK CASTING	FAA AD 49-27-02 SB NO.109	AS IN AD & SB	AS IN AD & SB
DGCA / PIPER PA-12/14	NICOPRESS SLEEVE REWORK	FAA AD 50-05-01	AS IN AD & SB	AS IN AD & SB
DGCA / PIPER PA-12/15	INSPECTION OF AILERON HINGE BRACKETS	FAA AD 51-21-02 SB NO.107	AS IN AD & SB	AS IN AD & SB
DGCA / PIPER PA-12/16	INSPECTION OF TAIL BRACEWIRES	FAA AD 60-01-03 SB NO.183 SL NO.400	AS IN AD & SB	AS IN AD & SB
DGCA / PIPER PA-12/17	CANCELLED VIDE LETTER NO.14-11-48-AI(1) DT.08-02-77			
DGCA / PIPER PA-12/18	INSPECTION OF ENGINE EXHAUST MUFFLER AND SHROUD ASSEMBLY	FAA AD 68-05-01	AS IN AD & SB	AS IN AD & SB
DGCA / PIPER PA-12/19	INSTALLATION OF FABRIC REINFORCEMENT STRIP TO PREVENT SUDDEN FAILURE OF FABRIC AT THE TOP OF WIND SHIELD	FAA AD 74-17-04 DT.11-04-77	AS IN AD & SB	AS IN AD & SB
DGCA / PIPER PA-12/20	FUEL TANK CAP MODIFICATION AND PROPER INSTALLATION OF FUEL TANK FILTER NECK AND 573 GASKET	FAA AD 78-10-03 AND PIPER SB NO.522 AND 573	AS IN AD & SB	AS IN AD & SB
DGCA / PIPER PA-12/21	REPETITIVE INSPECTION AND REPLACEMENT OF WING LIFT STRUTS AND WING LIFT STRUT FORKS	FAA AD 99-01-05 CF 80-24RI AND PIPER SB 910A AND SB 528D	AS IN AD & SB	AS IN AD & SB