

DGCA NO	SUBJECT	REFERENCE AD	COMPLIANCE	APPLICABILITY
DGCA/LYCO.IO,TIO 540/1	INSPECTION OF OIL PUMPS DRIVE SHAFT P/N 67512 FOR DAMAGE	FAA AD 63-14-3	AS IN AD	AS IN AD
DGCA/LYCO.IO,TIO 540/2	MODIFICATION OF A. C LIGHT WT. FUEL PUMPS	FAA AD 64-16-5	AS IN AD	AS IN AD
DGCA/LYCO.IO,TIO 540/3	REPLACEMENT OF OIL FILTER ADAPTER GASKET AND INSPECTION OF STUDS TAPED HOLES AND CAP SCREWS	FAA AD 66-20-4	AS IN AD	AS IN AD
DGCA/LYCO.IO,TIO 540/4	REPLACEMENT OF DELRIN STEMMED FUEL DIAPHRAGM ASSEMBLY WITH NEW PART NO	FAA AD 67-22-6	AS IN AD	AS IN AD
DGCA/LYCO.IO,TIO 540/5	INSTALLATION OF A PLACARD ON THE INSTRUMENT PANEL TO PREVENT FAILURE OF THE ENGINE CRANK SHAFT	FAA AD 69-8-9	AS IN AD	AS IN AD
DGCA/LYCO.IO,TIO 540/6	PISTON PIN FAILURES RESULTING FROM GRINDING CRACKS WHICH OCCURRED DURING MANUFACTURE	FAA AD 73-23-1	AS IN AD	AS IN AD
DGCA/LYCO.IO,TIO 540/7	100% REPLACEMENT OF ALL BIG END BEARING BOLTS	DGCA LETTER NO. 12/114/74-AI(1) DT. 6/3/75	AS IN DGCA LETTER	ALL LYCO ENGINES
DGCA/LYCO.IO,TIO 540/8	INSPECTION OF OIL PUMP DRIVE SHAFT AND DRIVE IMPELLER	FAA AD 75-8-9 DT. 17/12/75	AS IN AD	AS IN AD
DGCA/LYCO.IO,TIO 540/9	REPLACEMENT OF FUEL FLOW DIVIDER COVER GASKET TO PREVENT FUEL FLOW STARVATION	FAA AD 75-9-15	AS IN AD	AS IN AD
DGCA/LYCO IO,TIO 540/10	INSPECTION OF CONNECTING RODS FOR FRETTING AND GALLING	LYCO. S. B. 439	DURING ENGINE OVERHAUL	ALL LYCO ENGINES
DGCA/LYCO.IO,TIO 540/11	REPLACEMENT OF OIL PUMP DRIVEN IMPELLER AND SHAFT AND DRIVING IMPELLER	FAA AD 81-18-04 R2	AS IN AD	AS IN AD
DGCA/LYCO.IO,TIO 540/12	REPLACEMENT OF FUEL DIAPHRAGM ASSEMBLY ETC. BENDIX FUEL INJECTION SYSTEM	FAA AD 83-22-04 AVCO LYCO. S.B. 467 BENDIX ENERGY CONTROL DIVISION SB NO RS-85 & RS-88	AS IN AD	AS IN AD
DGCA/LYCO.IO.TIO 540/13	TO PREVENT FUEL INJECTION MANIFOLD TO NOZZLE TUBE ASSEMBLY FAILURES	FAA AD 71-13-01	AS IN AD	AS IN AD
DGCA/LYCO.IO,TIO 540/14	TO PREVENT AN FLIGHT POWERLESS DUE TO AN OVER RICH CONDITION CAUSED BY BELLOWS SEAL ASSY OF BENDIX FUEL INJECTOR MODEL	FAA AD 78-23-10	AS IN AD	AS IN AD
DGCA/LYCO.IO,TIO 540/15	TO PREVENT LOSS OF ENGINE POWER CONTROL DUE TO SEIZED TROTTLE MOVEMENT	FAA AD 80-17-10	AS IN AD	AS IN AD
DGCA/LYCO.IO,TIO 540/16	TO PREVENT POSSIBLE FAILURE OF THE ENGINE CYLINDER ASSY P/N LW-18852	FAA AD 84-19-03 R1	AS IN AD	AS IN AD
DGCA/LYCO.IO,TIO 540/17	INSPECTION AND REWORK OR REPLACEMENT OF ROCKER CAM ASSY P/N LW-18790	FAA AD 87-10-06 R1	AS IN AD	AS IN AD
DGCA/LYCO.IO,TIO 540/18	INSPECTION OF THE EXHAUST PIPES FLANGES AND V-BAND COUPLINGS FOR CRACKING OR DISTORTION AND REPLACEMENT OF CROSS OVER EXHAUST TUBE WITH A MODIFIED TUBE.	FAA AD 91-21-01	AS IN AD	AS IN AD
DGCA/LYCO.IO,TIO 540/19	ONE TIME LEAK CHECK OF ENGINE DRIVEN FUEL PUMP DIAPHRAGM AND INSPECTION OF PUMP FITTING.	FAA AD 91-08-07	AS IN AD	AS IN AD
DGCA/LYCO.IO,TIO 540/20	CANCELLED W.R.T DGCA /LYCOMING /O3 AS PER FAA AD 2004-10-14 dt 18-06-04			
DGCA/LYCO.IO,TIO 540/21	RECORD SEARCH/REMOVAL/REPLACEMENT OF PISTON PINS	FAA AD 92-12-05	AS IN AD	AS IN AD
DGCA/LYCO.IO,TIO 540/22	REMOVAL AND REPLACEMENT OF AFFECTED FUEL PUMPS.	FAA AD 93-11-11 AND AERO ACCESSORIES SB NO. 002 DTD	AS IN AD & SB	AS IN AD & SB

		25TH FEB'1993		
DGCA/LYCO.IO,TIO 540/23	TO PREVENT FAILURE OF FUEL INJECTOR FUEL LINES	FAA AD 2002-26-01	AS IN AD & SB	AS IN AD & SB
DGCA/LYCO.IO,TIO 540/24	FUEL INJECTOR NOZZLE ASSEMBLIES	LYCO MANDOTRY SB. NO. 510 AND PRECISION A C SB PRS -101	AS IN SB	AS IN SB
DGCA/LYCO.IO,TIO 540/25	TO PREVENT DETONATION DUE TO LOW OCTANE FUEL CAUSING ENGINE DAMAGE	FAA AD 94-14-13	AS IN AD	AS IN AD
DGCA/LYCO.IO,TIO 540/26	TO PREVENT ENGINE FAILURE DUE TO	FAA AD 95-07-01	AS IN AD	AS IN AD
DGCA/LYCO.IO,TIO 540/27	PREVENT CYLINDER HEAD SEPRATION, IN FLIGHT LOSS OF POWER	FAA 97-01-04	AS IN AD	AS IN AD
DGCA/LYCO.IO,TIO 540/28	TO PREVENT PISTON PIN FAILURE WHICH COULD RESULT IN ENGINE FAILURE	FAA 97-15-11	AS IN AD	AS IN AD
DGCA/LYCO.IO,TIO 540/29	INSPECTION OF CRANKSHAFT FOR CRACKS - VISUAL INSPECTIONS, MAGNETIVC PARTICLE INSPECTIONS & DIMENSIONAL CHECK OF CRANKSHAFT JOURNALS	FAA AD 98-17-11	AS IN AD	AS IN AD
DGCA/LYCO.IO,TIO 540/30	CANCELLED W.R.T. DGCA/LYCOMING/01			
DGCA/LYCO.IO,TIO 540/31	ENGINE CYLINDER EXHAUST VALVE & GUIDE - PERIODICAL INSPECTION	BLAAD 1994-046/03	AS IN AD	AS IN AD
DGCA/LYCO.IO,TIO 540/32	TO PREVENT COMPLETE LOSS OF ENGINE AFTER SUBSEQUENT SEIZING OF THE ENGINE	FAA AD 2002-12-07	AS IN AD	AS IN AD
DGCA/LYCO.IO,TIO 540/33	TO PREVENT CRANKSHAFT FAILURE	FAA AD (EMERGENCY) 2002-19-03	AS IN AD	AS IN AD
DGCA/LYCO.IO,TIO 540/34	CANCELLED W.R.T. DGCA / LYCOMING / 02			
NEXT ONWARDS	PLEASE FOLLOW " DGCA / LYCOMING / " LIST.	END	END	END