

SL NO	DGCA AD No	SUBJECT	REFERENCE	PREVIOUS REFERENCE	COMPLIANCE	APPLICABILITY
01.	DGCA/AGUSTA/AW139/01R2	Fuselage- Tail Boom - Inspection	EASA AD 2011- 0019	EASA AD 2009- 0234-E R1	AS IN AD	AS IN AD
02.	DGCA/ AGUSTA /AW139/02	Fuselage-Wire Strike Protection System (WSPS) Top Cable Cutter-Rework/Replacement	EASA AD 2008- 0148	-----	AS IN AD	AS IN AD
03.	DGCA/ AGUSTA /AW139/03	Windows-Cockpit Door ,Windows-Replacement	EASA AD 2008- 0108	-----	AS IN AD	AS IN AD
04.	DGCA/ AGUSTA /AW139/04	[Corrected] Stabilizers-Fin Assembly-inspection/Replacement	EASA AD 2006- 0358	-----	AS IN AD	AS IN AD
05.	DGCA/ AGUSTA /AW139/05	Exhaust-Tailpipe Assembly-Inspection/Repair/Replacement	EASA AD 2006- 0360-E & FAA AD 2007- 25- 14	FAA AD 2006-17-51	AS IN AD	AS IN AD
06.	DGCA/ AGUSTA /AW139/06R1	Fuselage-Frame 5700 Middle Section-Inspection	EASA AD 2006- 0357R1	EASA AD 2006- 0357R1 FAA AD 2008-14- 02	AS IN AD	AS IN AD
07.	DGCA/ AGUSTA /AW139/07	ELECTRICAL POWER ---- GENERATOR CONTROL UNIT(GCU)--- REPLACEMENT	EASA AD 2009 - 0042		AS IN AD	AS IN AD
08	DGCA/ AGUSTA /AW139/08R3	EQUIPMENT / FURNISHINGS --- SPECTROLAB NIGHTSUN XP SEARCHLIGHT --- INSPECTION/ REMOVAL/REPLACEMENT	EASA AD 2010 - 0237 R2	EASA AD 2010 - 0237 R1	AS IN AD	AS IN AD
09	DGCA/ AGUSTA /AW139 / 09	NAVIGATION – MODULAR AVIONIC UNIT – INSPECTION / REPLACEMENT / MODIFICATION	EASA AD 2010-0189		AS IN AD	AS IN AD
10	DGCA/ AGUSTA /AW139 / 10 R1	TAIL ROTOR --- TAIL ROTOR BLADES --- INSPECTION /REPLACEMENT (REDUCED LIFE LIMITATION)	EASA AD 2011-0156-E	EASA AD 2011-0081	AS IN AD	AS IN AD
11	DGCA/ AGUSTA /AW139 / 11	ATA 23- COMMUNICATIONS - PRIMUS EPIC HARNESSSES SOLDER SPLICES - INSPECTION/REPLACEMENT	EASA AD 2011-0140		AS IN AD	AS IN AD