

| SERIAL NO | DGCANO | SUBJECT | REFERENCE | PREVIOUS REF | COMPLIANCE | APPLICABILITY |
|-----------|-----------------------|--|--------------------------|---------------------|-----------------|-----------------|
| 1 | DGCA/AGUSTA A119/01 | INSPECTION OF TAIL ROTOR BLADE | ITALY AD 2001-374 | | AS IN AD AND SB | AS IN AD AND SB |
| 2 | DGCA/AGUSTA A119/02 | REMOVAL OF CERTAIN TAIL ROTOR BLADE FROM SERVICE | ITALY AD 2001-426 | | AS IN AD AND SB | AS IN AD AND SB |
| 3 | DGCA/AGUSTA A119/03 | REPLACEMENT OF VERTICAL GYROSCOPE | ITALY AD 2002-004 | | AS IN AD AND SB | AS IN AD AND SB |
| 4 | DGCA/AGUSTA A119/04 | REPLACEMENT OF HYDRAULIC PUMP | ITALY AD 2002-113 | | AS IN AD AND SB | AS IN AD AND SB |
| 5 | DGCA/AGUSTA A119/05 | MODIFY THE ELECTRICAL INSTALLATION OF WINDSHIELD WIPERS | ITALY AD 2002-309 | | AS IN AD AND SB | AS IN AD AND SB |
| 6 | DGCA/AGUSTA A119/06 | INSPECTION OF TAIL ROTOR BLADE AND REPLACEMENT OF THE BUSHING FITTED ON THE TAIL ROTOR GRIPES. | ITALY AD 2002-367 | | AS IN AD AND SB | AS IN AD AND SB |
| 7 | DGCA/AGUSTA A119/07 | CHECK OF BOLTS SECURING THE TRANSMISSION SUPPORT FITTINGS TO THE STRUCTURE. | ITALY AD 2004-108 | | AS IN AD AND SB | AS IN AD AND SB |
| 8 | DGCA/AGUSTA A119/08 | TAIL ROTOR - TAIL ROTOR PITCH CONTROL LINK ASSY P/N 109-0130-05-117 | EASA AD 2006-228E | | AS IN AD AND SB | AS IN AD AND SB |
| 9 | DGCA/AGUSTA A119/09 | EQUIPMENT & FURNISHINGS --- CARGO HOOK P/N 528 - 010 - 01/ LEVER P/N 232 - 028 - 00 - INSPECTION | EASA AD 2007-0160 -E | | AS IN AD AND SB | AS IN AD AND SB |
| 10 | DGCA/AGUSTA A119/10 | HYDRAULIC POWER -- HYDRAULIC PIPES P/N'S 109 - 0761- 64 -103 & 109 - 0761- 65 -103 -- INSPECTION /REPLACEMENT | EASA AD 2007- 0231 | | AS IN AD AND SB | AS IN AD AND SB |
| 11 | DGCA/AGUSTA A119/11 | FUSELAGE --- PILOT & CO-PILOT DOOR HOUSING SLOTS --- INSPECTION / MODIFICATION | EASA AD 2007- 0295R1 - E | | AS IN AD AND SB | AS IN AD AND SB |
| 12 | DGCA/AGUSTA A119/12 | ROTORS FLIGHT CONTROL --- TAIL ROTOR(T/R) ADJUSTABLE ROD ASSEMBLY --- IDENTIFICATION / REPLACEMENT | EASA AD 2009- 0231 - E | | AS IN AD AND | AS IN AD AND |
| 13 | DGCA/AGUSTA A119/13 | TAIL ROTOR DRIVE --- TAIL ROTOR GEARBOX ASSEMBLY --- INSPECTION/REPLACEMENT/RE-IDENTIFICATION | EASA AD 2010 -0059-E | | AS IN AD AND | AS IN AD AND |
| 14 | DGCA/AGUSTA A119/14 | ABNORMAL VIBRATION AND DAMAGE TO THE TAIL ROTOR SYSTEM,LOSS OF YAW CONTROL FUNCTION AND SUBSEQUENT LOSS OF CONTROL OF THE HELICOPTER | FAA AD 2010-12-51 | | AS IN AD AND | AS IN AD AND |
| 15 | DGCA/AGUSTA A119/15R1 | ROTORS FLIGHT CONTROL --- PILOT & COPILOT CONTROL BOX ASSEMBLIES --- INSPECTION/REPLACEMENT | EASA AD 2011-0095-E | EASA AD 2010-0142-E | AS IN AD AND | AS IN AD AND |