

DGCA NO	Subject	Reference AD	Compliance	Applicability
DGCA/ROTOL/001	RENEWAL OF BLADE CORROSION AND SUBSEQUENT PROTECTION	DOWTY ROTOL SB NOS.61-266 B, 61-266 C, 61-266 E, 61-266 A	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/002	INTRODUCTION OF LONGER BOLTS CONTROLLER UNIT	SB.NO.61-273	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/003	INTRODUCTION OF REVISED RESTRICTER CONTROLLER UNIT	SB.NO.61-341	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/004	REVISED EYEBOLT GUIDE SEALING CYLINDER GROUP	SB.NO.61-365	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/005	REWORK OF BLADE BEARINGS	S.B.NO.61-380-TNS NO.339 ISSUE 1	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/006	INSPECTION OF PROPELLERS CYLINDERS CRACKING THROUGH FRONT THREADS	S.B.NO.61-521 AND 61-521 REV.4	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/007	DELETION OF PIPE FROM FILTER ELBOW. OIL PUMP GROUP	SB.NO.83-275	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/008	INTRODUCTION OF NEW GEAR BEVEL PINION	SB.NO.83-291	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/009	INTRODUCTION OF PRE-PRIMER FOR PROPELLER BLADES	SB.NO.61-157	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/010	PROHIBITION OF ENGINE TEST FAN FOR FLIGHT PURPOSES	DOWTY SB.NO.61-251	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/011	ADDITION TO BREATHER TO GEAR CHAMBER-FEATHERING UNIT	ROTOL MOD.F.P.83	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/012	CRIMPING OF LEAD CONNECTION (MOD.F.P 64) OR IMPROVED TYPE SOLDERED PINS (MOD FP 79) AND PLUG ADAPTER FACE MACHINED ON B.T.H. MOTORS	ROTOL MOD.F.P.98	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/013	DELETION OF NON-RETURN VALVE DRIVING GEAR	ROTOL MOD F.P.98	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/014	ADDITION OF LOCATING SLEEVE TO STEM OF THIRD OIL VALVE ASSEMBLY	ROTOL MOD GU 642	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/015	REDUCTION OF GOVERNOR MINIMUM RPM SETTING	ROTOL MOD.GU 625	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/016	SPLITTING OF HUB AND CENTRE ASSEMBLIES FOR CRACKS DETECTION AND CORROSION PROTECTION	DOWTY ROTOL SB.NO.168 B	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/017	PROPELLERS AND ANCLARY EQUIPMENT ULTIMATE LIVES OF COMPONENTS	DOWTY ROTOL SB.NO.61-542, 61-542-1 REV.2, 61-542 REV.3, 61-542-3, 61-542-4, 61-542-5 AND 61-542-6 REV.2	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/018	ASSEMBLY OF HUB AND DRIVING CENTRE	DOWTY ROTOL SB NO.61-573 B	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/019	INTRODUCTION OF NEW OPERATING CYLINDER	DOWTY ROTOL SB.NO.61-564 REV.6	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/020	INTRODUCTION OF REVISED CABIN BLOWER QUILL SHAFT	DOWTY ROTOL SB.NO.83-407 REV.2	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'

DGCA/ROTOL/021	INSPECTION OF PROPELLER OPERATING PINS FOR CRACK	DOWTY ROTOL SB.NO.61-33, DOWTY ROTOL SB NO.61-A734	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/022	INSPECTION OF PROPELLER OPERATING PINS FOR CRACK	DOWTY ROTOL SB.NO.61-740	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/023	INSPECTION OF PROPELLER OPERATING PINS FOR CRACKING AT OVERHAUL	DOWTY ROTOL SB.NO.61-711 REV.3	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/024	INSPECTION OF PROPELLER OPERATING LINK GROUP PARTS AND EYEBOLT FOR UNDESIRABLE CAD PLATING	DOWTY ROTOL SB NO.61-A753	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/025	ONE TIME DE-EMBRITTEMENT HEAT SOAK OR WRONGLY CAD-PLATED COMPONENTS	DOWTY ROTOL SB.NO.61-754	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/026	REDUCTION OF SHEAR NECK DIA. OF QUILL DRIVE OF CABIN BLOWER	DOWTY ROTOL SB.NO.83-402 REV.2 DT.NO.70	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/027	REDUCTION OF SHEAR-NECK DIA. OF QUILL DRIVE OF CABIN BLOWER	DOWTY ROTOL SB.NO.83-417 REV.1 DT.NOVEMBER 70	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/028	REPLACEMENT OF LOCKING SEGMENTS USED FOR BLADE BEARING RETAINING BOLTS	FAA.AD.72-14-1 DOWTY ROTOL SB 61-714 REV.3 DT.26.07.71	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/029	REPLACEMENT OF THE CABIN SUPERCHARGER DRIVE QUILL SHAFT WITH THE ONE HAVING A PROOF FACTOR OF 1.69	DOWTY ROTOL SB.NO.83-378 REV..2 DT. NOVEMBER 70.	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/030	INSPECTION OF PROPELLER HUB FOR CRACKS IN FRONT WALL	CAA.AD.006-03-88 AND DOWTY ROTOL SB.NO.61-1053 REV.1 DT.18.01.88	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/031	INSPECTION OF HUB DRIVING CENTRES FOR INCORRECT MACHINING	DOWTY ROTOL S.B.NO.61-857 REV.1 AND FAA.AD.770907	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/032	INCORPORATION OF STRENGTHENED HUBS AND HUB DRIVING CENTRE ASSEMBLY	DOWTY ROTOL SB.NO.61-604 REV.2 MOD.(C) VP 2388 REV.3	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/033	INSPECTION / RECTIFICATION OF CORROSION OF THE PROPELLER BLADES	DOWTY ROTOL S.B.NO.61-888 REV.1 B;A.AD.NO.70-61 FOKKER SB.F27/61-32	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/034	ULTIMATE LIFE OF HOLE AND DRIVING	DOWTY ROTOL SB.NO.61-542-18 REV.1	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/035	INSPECTION OF HUB AND DRIVING ASSEMBLY CORROSION	FAA.AD.78-09-03 AND F27 SB.NO.61-31	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/036	INSPECTION OF HUB FOR CRACKS IN FRONT WALL	BLA AD 79-08-61 DOWTY ROTOL SB 61-909 F 27 S.B.NO.61-344 REEV.2	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/037	PROPELLERS-PITCH LOCK GROUP CRACKING OF CYLINDER COVER	CAA.AD.011-10-86 AND DOWTY ROTOL SB 61-1043 REV.4 DT.11.03.88	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/038R2	PROPELLERS- HUB AND DRIVING CENTRE ASSEMBLY --- INSPECTION/REPLACEMENT	EASA AD 2011 - 0012	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/039	INSPECTION AND REPLACEMENT OF HUB CONTACT SWITCH BRUSHES	CAA.AD.007-03-88 AND DOWTY ROTOL SB.NO.61-1054	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/040	PROPELLERS - OPERATING CYLINDER RETAINING BOLTS - REPLACEMENT	BLA AD.91-135/2 (A) AND BLA.AD. 93-01-130 (A)	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'

DGCA/ROTOL/041	PROPELLER OVERSPEED GOVERNOR - NEW WEIGHTS AND CARRIER ASSEMBLY	CAA 002-04-098	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/042R2	PROPELLERS -- PROPELLER HUB --- INSPECTION/REPLACEMENT	EASA AD 2010-0196R1	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/043	TO PREVENT BLADE COUNTERWEIGHT RELEASE,WHICH COULD RESULT IN INJURY OR DAMAGE TO THE AIRPLANE	EASA AD 2010-05-09	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'
DGCA/ROTOL/044	TO PREVENT SEIZURE OR EMBRITTLEMENT & CRACKING OF THE BLADE PITCH CHANGE OPERATING LINKS & EYEBOLT FORK ASSEMBLIES	FAA AD 2010-10-23	'AS IN AD & SUBSEQUENT REVISIONS TO SB'	'AS IN AD & SUBSEQUENT REVISIONS TO SB'