

SI No	DGCA NO	SUBJECT	AD REFERENCE	COMPLIANCE	APPLICABILITY
1	DGCA/HOFFMANN/01	STRENGTH PROBLEMS ON PROPELLER MOUNTING BOLTS	LBA AD 1998-322/2	AS IN AD AND SB	AS IN AD AND SB
2	DGCA/HOFFMANN/02	POSSIBLE HUB FAILURE DUE TO UNKNOWN REASONS	LBA AD 2004-352 R4	AS IN AD AND SB	AS IN AD AND SB
3	DGCA/HOFFMANN/03	RUPTURE OF PITCH CONTROL RODS DUE TO FATIGUE PROBLEMS	LBA AD 2005-370	AS IN AD AND SB	AS IN AD AND SB