

DGCANO	SUBJECT	REFERENCE	COMPLIANCE	APPLICABILITY
DGCA / ISLANDER BN 2 & 2A / 1	INSPECTION OF TAIL PLANE ELEVATOR TRIM TAB AND ATTACHMENTS	BN-2 / SB 1	AS IN SB	AS IN SB
DGCA / ISLANDER BN 2 & 2A / 2	CHANGE OF SEAT WEBBING	BN-2/NB/M/233 OR M295	AS IN SB	APPLICABLE TO ALL A PRIOR TO CONSTRUCTO 19 SHOULD HAVE BEEN EMBODIES BY 30TH MA BN-2/SB 5 ALSO REFE
DGCA / ISLANDER BN 2 & 2A / 3	RUDDER CONTROL CABLES-PREVENTION OF INADVERTENT CROSS CONNECTION	BN-2/NB/M/294	AS IN SB	AS IN SB
DGCA / ISLANDER BN 2 & 2A / 4	INSPECTION OF FUEL PIPE BETWEEN ENGINE DRIVEN PUMP AND CURBURETOR	BN-2/SB 11	AS IN SB	AS IN SB
DGCA / ISLANDER BN 2 & 2A / 5	INSPECTION OF TURNBUCKLES IN AILERON RUDDER AND NOSE WHEEL STEERING CONTROL SYSTEMS	BN-2/SB 15	AS IN SB	AS IN SB
DGCA / ISLANDER BN 2 & 2A / 6	RUDDER BAR BEAM DEFECTS	BN-2/SB 20	AS IN SB	AS IN SB
DGCA / ISLANDER BN 2 & 2A / 7	UNINTENTIONALLY KEPT BLANK			
DGCA / ISLANDER BN 2 & 2A / 8	LOOSE LOCKING KEYSIN WING ATTACHMENT SPINDLES	BN-2/SB 25	AS IN SB	AS IN SB
DGCA / ISLANDER BN 2 & 2A / 9	TO INTRODUCE A CHANGE OF ELEVATOR TRIM TAB ANGLE	BN-2/NB/M/179	AS IN MOD	AS IN MOD
DGCA / ISLANDER BN 2 & 2A / 10	INSPECTION OF TAIL PLANE FRONT SPAR ATTACHMENTS	BN-2/SB 27	AS IN SB	AS IN SB
DGCA / ISLANDER BN 2 & 2A / 11	FIRE HAZARD IN CURBURETOR AIR BOXES	BN-2/SB 28	AS IN SB	AS IN SB
DGCA / ISLANDER BN 2 & 2A / 12	INSPECTION OF FLAP OPERATING LEVER AND FLAP ATTACHMENTS	BN-2/SB 36 ISSUE 3	AS IN SB	AS IN SB
DGCA / ISLANDER BN 2 & 2A / 13	REINFORCEMENT OF THE FLAP CENTRE OPERATING LEVER	BN-2/NB/M/417	AS IN MOD	AS IN MOD
DGCA / ISLANDER BN 2 & 2A / 14	LOOSE JO-BOLTS IN THE ENGINE MOUNING FRAME ATTACHMENT BRACKETS	BN-2/SB 44 ISSUE 3	AS IN SB	AS IN SB
DGCA / ISLANDER BN 2 & 2A / 15	TO CHANGE THE EYE-END OF THE ELEVATOR TRIM JACK	FAA AD 71-05-05 & BN-2/BNB/M/468	AS IN SB	AS IN SB
DGCA / ISLANDER BN 2 & 2A / 16	CANCELLED VIDE HEADQUARTERS LETTER NO. 9-457/81 VOL III DATED 21ST MAY 1983			
DGCA / ISLANDER BN 2 & 2A / 17	INTRODUCTION OF NEW ELEVATOR TRIM TAB	BN-2/NB/M/507	AS IN SB	AS IN SB
DGCA / ISLANDER BN 2 & 2A / 18	REPLACEMENT OF PROPELLER GOVERNOR DRIVE GEAR WITH MODIFIED GEAR	BN-2/SB 53 ISSUE 4 DT.7/10/76 & WOODWARD SB 33538 & 33539	AS IN SB	AS IN SB
DGCA / ISLANDER BN 2 & 2A / 19	DEFECTS IN UPPER ENGINE MOUNTING BRACKETS FOR WING MOUNTED ENGINES	FAA AD 84-23-06 AND BN-2/SB 61 ISSUE 5	AS IN SB	AS IN SB
DGCA / ISLANDER BN 2 & 2A / 20	INSPECTION AND REPLACEMENT OF SANGAMO WESTON TACHOMETER P/N S 128.5.139	BN-2/SB 68	AS IN SB	AS IN SB
DGCA / ISLANDER BN 2 & 2A / 21	INSPECTION AND STRENGTHENING OF FLIGHT COMPARTMENT SEAT BACKS	BN-2/SB 69	AS IN SB	AS IN SB
DGCA / ISLANDER BN 2 & 2A / 22	DEFECTIVE SEAT LOCKING MECHANISM OF FLIGHT COMPARTMENT SEATS	BN-2/SB 71 ISSUE 269	AS IN SB	AS IN SB
DGCA / ISLANDER BN 2 & 2A / 23	ENGINE MOUNTNG FRAME WELD INSPECTION	BN-2/SB 72	AS IN SB	AS IN SB
DGCA / ISLANDER BN 2 & 2A / 24	RUDDER HINGE BEARING AT TOP OF FIN POST	BN-2/SB 76 ISSUE 4	AS IN SB	AS IN SB

DGCA / ISLANDER BN 2 & 2A / 25	CANCELLED VIDE LETTER NO.6-291/76-AI(2) DT. 9-3-1976			
DGCA / ISLANDER BN 2 & 2A / 26	INSPECTION / REPLACEMENT OF THE RUDDER BAR UNITS	FAA AD 75-24-07 R1 & BRITTON NORMAN SB NO. BN-2/56 ISSUE 2	AS IN AD & SB	AS IN AD & SB
DGCA / ISLANDER BN 2 & 2A / 27	INSPECTION / MODIFICATION OF THE RUDDER TOP, CENTRE AND BOTTOM HINGE STRUCTURES FOR CRACKS	FAA AD 75-26-01	AS IN AD & SB	AS IN AD & SB
DGCA / ISLANDER BN 2 & 2A / 28	INSPECTION / MODIFICATION OF THE AILERON MASS BALANCE CLAMP UNIT ATTACHMENT FOR LOOSENESS	FAA AD 96-18-21	AS IN AD & SB	AS IN AD & SB
DGCA / ISLANDER BN 2 & 2A / 29	INSPECTION / REPLACEMENT OF THE ENGINE MOUNTING FRAME AND THE MOUNTING PADS	FAA AD 76-02-04	EFFECTIVE FROM 1/3/1976	APPLICABLE TO BN-2A III AIRPLANES
DGCA / ISLANDER BN 2 & 2A / 30	INSPECTION / MODIFICATION OF THE PILOT'S SEAT	FAA AD 76-06-05	EFFECTIE FROM 1/5/1975	AS IN AD & SB
DGCA / ISLANDER BN 2 & 2A / 31	RUDDER LOWER BAR MOUNTING DEFFECTS	BRITTEN NORMAN SB NO. BN-2/74	AS IN SB	AS IN AD
DGCA / ISLANDER BN 2 & 2A / 32	CORROSION OF ENGINE MOUNT BRACKETS	BRITTEN NORMAN S.B. NO.BN-2/SB.91 REV 76-21-07	AS IN SB	AS IN SB
DGCA / ISLANDER BN 2 & 2A / 33	DETECTION / RECTIFICATION OF CORROSION INSIDE AILERON MASS BLANCE TUBE	FAA AD 77-07-10	WITHIN 30.12.76	AS IN AD
DGCA / ISLANDER BN 2 & 2A / 34	INSPECTION AND PROTECTION AGAINST ELECTROLYTIC CORROSIVE ACTION - CONTROL RODS	BRITTEN NORMAN S.B BN-2/S.B. 101 ISSUE 2 DT 10-8-77 & FAAD 78-11-08	1-10-77 OR NEXT 50 HRS INSP WHICHEVER IS EARLIER AND THEN AT EACH 100 HRS INSP	AS IN SB
DGCA / ISLANDER BN 2 & 2A / 35	FLAME RETARDENT HOLD DOWN COVERS ON AIRCRAFT BATTERIES MANUFACTURED BY CHLORIDE INDUSTRIAL BATTERIES	BRITTEN NORMAN S.B. NO. BN-2/SB.140 ISSUE 1	31-3-80	AS IN SB
DGCA / ISLANDER BN 2 & 2A / 36	CONVERSION OF MAIN UNDER CARRIAGE LEGS PT NO AIR 46200	AP PRECISION HYDRAULICS S.B. NO. 32-277 REV 1	31-3-80	AS IN SB
DGCA / ISLANDER BN 2 & 2A / 37	INSPECTION / REPLACEMENT / MODIFICATION OF CARB AIR BOX SHUTTERS	PILATUS BRITTEN NORMAN S.B. NO. BN-2/SB. 144 ISSUE 1 FAAD NO. 82-24-06R1	AS IN AD	AS IN AD
DGCA / ISLANDER BN 2 & 2A / 38	CANCELLED VIDE HQRS LETTER NO. 9-457/81-AI(2) VOL III DATED 11/6/93			
DGCA / ISLANDER BN 2 & 2A /39	INSPECTION AND REINFORCEMENT OF ATTACHMENT BRACKETS OF TELEFLEX SWIVEL ASSEMBLIES OF PROPELLER & ENGINE CONTROLS	FAA AD 83-05-02 & BN SB NO.BN-2/SB 109 ISSUE 111	AS IN AD	AS IN AD
DGCA / ISLANDER BN 2 & 2A / 40	INSPECTION AND / OR REPLACEMENT OF WING TIP TANK FUEL TRANSMITTER FLOATS	FAA AD NO. 83-07-12 & B.N. S.B. NO. BN-2/SB NO.BN2 /SB142 ISSUE 3	AS IN AD	AS IN AD AND R1
DGCA / ISLANDER BN 2 & 2A / 41	INSPECTION OF ELEVATOR TRIM TAB DEFECTS AND REPLACEMENT OF DEFECTIVE PARTS	FAA AD 83-10-06 REV 1	AS IN AD	AS IN AD
DGCA / ISLANDER BN 2 & 2A / 42	TAILPLANE - INSPECTION FOR LOOSE RIVETS AND DAMAGE TO TAILPLANE SKIN AND STRUCTURE EXTENDING FROM ROOT RIBS AND REARWARDS TO SPARS	PILATUS BRITTEN NORMAN S.B. NO. BN-2/SB 131	AS IN SB	AS IN SB

DGCA / ISLANDER BN 2 & 2A / 43	TO DETECT CRACKS IN THE MLG AT JUNCTION OF TORQUE LINK LUG	FAA AD 86-07-02 SB NO.BN-2/SB 170 ISSUE 2	AS IN AD & SB	AS IN AD & SB
DGCA / ISLANDER BN 2 & 2A / 44	ELEVATOR MASS BALANCE DEFECT	BRITTON NORMAN MANDATORY SB NO. BN-2/SB 113 ISSUE:2	AS IN SB	AS IN SB
DGCA / ISLANDER BN 2 & 2A / 45	INSPECTION OF PROPELLER HUBS FOR CRACKING	EMERGENCY TELEX CAA AD NO.009-08-86	AS IN AD	AS IN AD
DGCA / ISLANDER BN 2 & 2A / 46	ELECTRICAL POWER POSSIBLE ACCIDENTAL SHORT - CIRCUIT AT REAR OF PILOTS SWITCH PANEL PREVENTIVE MEASURE	CAA AD 020-06-91	BEFORE 1ST FEB 92 AVAILABILITY OF KIT WHICHEVER IS EARLIER	AS IN AD
DGCA / ISLANDER BN 2 & 2A / 47	ENGINE FUEL AND CONTROL - REPLACEMENT OF COMPOSITE FLOATS WITH METAL FLOATS IN MARVEL SCHEBLER CUBUR	CAA AD 010-10-91	BEFORE 1ST FEB 92 AVAILABILITY OF KIT, WHICHEVER IS EARLIER	AS IN AD
DGCA / ISLANDER BN 2 & 2A / 48	PREVENT FAILURE OF NOSE WHEEL STEERING SYSTEM	FAA AD 95-04-09 SB NO BN-2/SB.214	AS IN AD	AS IN AD & SB
DGCA / ISLANDER BN 2 & 2A / 49	ENGINE FUEL AND CONTROL - CONTROL CABLE SWIVEL UNIT MOUNTING BRACKET FAILURE	CAA AD 009-05-95	AS IN AD	AS IN AD
DGCA / ISLANDER BN 2 & 2A / 50	FLIGHT CONTROLS - RUDDER CONTROL CABLES - INCORRECT ASSEMBLY	CAA AD 005-06-95	AS IN AD	AS IN AD
DGCA / ISLANDER BN 2 & 2A / 51	ELECTRICAL POWER 70 AMP DC GENERATION SYSTEM, REPLACE TYPE 10B1 OR 10D1 DIODES	CAA AD 004-01-96	AS IN AD	AS IN AD & SB
DGCA / ISLANDER BN 2 & 2A / 52	GENERATOR SYSTEM INSTALLED	CAA AD 007-10-96 BN-2/SB 229	AS IN AD & SB	AS IN AD & SB
DGCA / ISLANDER BN 2 & 2A / 53	TORQUE LODING OF ATTACHMENT BOLTS	CAA AD 008-10-96 BN-2/SB 231	AS IN AD & SB	AS IN AD & SB
DGCA / ISLANDER BN 2 & 2A / 54	WINGS - WING SPAR CAPS - INSPECTION	CAA AD 009-10-97	AS IN AD & SB	AS IN AD & SB
DGCA / ISLANDER BN 2 & 2A / 55	NG CELLES / PYLONS - EXAMINE AND REPAIR THE NG CELLES BOX STRUCTURE AT THE BOTTOM OF THE MAIN LANDING GEAR	CAA 011-10-97	AS IN AD & SB	AS IN AD & SB
DGCA / ISLANDER BN 2 & 2A / 56	ENGINE CONTROLS - THROTTLE FRICTION ADJUSTER - INSPECTION	CAA AD 004-03-2000	AS IN AD & SB	AS IN AD & SB
DGCA / ISLANDER BN 2 & 2A / 57	STABILISERS - ELEVATOR OUTBOARD - HINGE, INBOARD - BRACKET - INSPECTION & REPLACEMENT	CAA AD 005-03-2000	AS IN AD & SB	AS IN AD & SB
DGCA / ISLANDER BN 2 & 2A / 58	INSPECTION OF OLEO ATTACHMENT - BRACKETS AT THE BOTTOM OF THE MLG	CAA AD 005-09-2000 SB-273	AS IN AD & SB	AS IN AD & SB
DGCA / ISLANDER BN 2 & 2A / 59	CORROSION AFFECTING PRIMARY STRUCTURE	CAA AD 020-02-90 & BN-2/SB-190	AS IN AD & SB	AS IN AD & SB
DGCA / ISLANDER BN 2 & 2A / 60	FUSELAGE - INSTALLATION OF RUDDER LOWER HINGE DOUBLER	CAA AD 005-03-99 BN-2/SB 240	AS IN AD & SB	AS IN AD & SB
DGCA / ISLANDER BN 2 & 2A / 61	FLIGHT CONTROLS - CONTROL COLUMN SLIDING TUBE	CAA AD 006-03-99 & BN 2 / SB 243	AS IN AD & SB	AS IN AD & SB
DGCA / ISLANDER BN 2 & 2A / 62	WINDOWS - EMERGENCY EXIT WINDOW SEAL	CAA AD 001-08-2001	AS IN AD & SB	AS IN AD & SB

DGCA / ISLANDER BN 2 & 2A / 63	TO DETECT & CORRECT LOOSENING OF THE THROTTLE FRICTION ADJUSTMENT	FAA AD 2002-01-11AND CAA AD 003-07-2000	AS IN AD & SB	AS IN AD & SB
DGCA / ISLANDER BN 2 & 2A / 64	NACELLES/PYLONS - INSPECTION OF ENGINE MOUNTING BRACKETS	CAA AD 005-11-2001	AS IN AD & SB	AS IN AD & SB
DGCA / ISLANDER BN 2 & 2A / 65	POWER PLANT - CRACKING OF TURBINE ENGINE MOUNTING FRAME	CAA AD 002-05-2002	AS IN AD & SB	AS IN AD & SB
DGCA / ISLANDER BN 2 & 2A / 66	FLIGHT CONTROL - CONTROL COLUMN UNIVERSAL JOINT, SUPPLIES OF UNDERSIGNED COMPONENTS	CAA AD 004-05-2002	AS IN AD & SB	AS IN AD & SB
DGCA / ISLANDER BN 2 & 2A / 67	CONTROL ROD TO ELEVATOR TRIM TAB LEVER BOLT RETAINER	CAA AD 002-05-2003	AS IN AD & SB	AS IN AD & SB
DGCA / ISLANDER BN 2 & 2A / 68	EQUIPMENT & FURNISHING - PASSENGER SEATS - INSPECTION	CAA AD G-2003-0012	AS IN AD & SB	AS IN AD & SB
DGCA / ISLANDER BN 2 & 2A / 69	LANDING GEAR - RETIREMENT LIVES	CAA AD G-2003-0013	AS IN AD & SB	AS IN AD & SB
DGCA / ISLANDER BN 2 & 2A /70	FLIGHT CONTROLS, ELEVATOR, FINAL DRIVE INSPECTION	CAA-AD-G-2004-0011	AS IN AD & SB	AS IN AD & SB
DGCA / ISLANDER BN 2 & 2A /71(R1)	STABILISERS- HORIZONTAL STABILISER INSPECTION	CAA AD G-2004-0014(R1)	AS IN AD & SB	AS IN AD & SB
DGCA / ISLANDER BN 2 & 2A /72(R1)	NAVIGATION- PITOT/STATIC PRESSURE HEAD- INSPECTION AND TEST	EASA AD 2006-0143 (UK CAA AD G-2005-0034 IS CANCELLED)	AS IN AD & SB	AS IN AD & SB
DGCA / ISLANDER BN 2 & 2A / 73(R2)	FLIGHT CONTROLS --- ELEVATOR TIP ASSEMBLIES --- INSPECTION/REPLACEMENT	EASA AD 2009 - 0105R2	AS IN AD & SB	AS IN AD & SB