

DGCA NO	SUBJECT	REFERENCE	COMPLIANCE	APPLICABILITY
DGCA / PT-6A / 1	INSPECTION OF PROPELLER REVERSING CONTROLS	FAA AD 68-05-03	'AS IN AD'	'AS IN AD'
DGCA / PT-6A / 2	MODIFICATION OF FUEL PUMP DRIVE TO PREVENT DISENGAGEMENT	TC AD CF 69-17	'AS IN AD'	'AS IN AD'
DGCA / PT-6A / 3	INSPECTION AND REPLACEMENT OF COIL RETAINING SCREWS OF LOCK SOLENOID VALVE ON WOODWARD PROPELLER GOVERNORS	FAA AD 70-16-01	'AS IN AD'	'AS IN AD'
DGCA / PT-6A / 4	DETECTION OF ENGINE FAILURE AND SPECIALLY REDUCTION GEAR BOX DETERIORATION IN ENGINES WITH A REDUCED STRENGTH POWER TURBINE SHAFT HOUSING	FAA AD 75-06-01	'AS IN AD'	'AS IN AD'
DGCA / PT-6A / 5	ENGINE DISTRESS ESPECIALLY IN REDUCTION GEAR BOX OF ENGINES INCORPORATING POWER TURBINE SHAFT HOUSING ASSEMBLY P/N 3010548 YET UNMODIFIED	FAA AD 75-11-04	'AS IN AD'	'AS IN AD'
DGCA / PT-6A / 6	MODIFICATION OF NO.2 BEARING COVER ASSEMBLY BY ENCREASING THE COOLING HOLE DIAMETERS	TC AD CF 78-14	'AS IN AD'	'AS IN AD'
DGCA / PT-6A / 7	TO MINIMISE THE CHANCE OF POWER TURBINE DISC RELEASE IN THE EVENT OF DECOUPLING	TC AD CF 78-03	'AS IN AD'	'AS IN AD'
DGCA / PT-6A / 8	INSPECTION OF FUEL PUMP DRIVE COUPLING FOR WEAR AND DAMAGE	FAA AD 80-08-12	'AS IN AD'	'AS IN AD'
DGCA / PT-6A / 9	HOT SECTION INSPECTION	P&W SB NO. 1003 REV.28 & SB 1803 R1	'AS IN AD'	'AS IN AD'
DGCA / PT-6A / 10	ENGINE TURBINE / TURBOPROP ROTOR COMPONENTS SERVICE LIFE	FAA AD 86-10-05 & TC AD CF 83-28	'AS IN AD'	'AS IN AD'
DGCA / PT-6A / 11	ROTOR COMPONENTS - SERVICE LIFE	P&W SB NO. 1002 R14	'AS IN AD'	'AS IN AD'
DGCA / PT-6A / 12	CANCELLED VIDE DGCA 9-504/77-AI(2) DATED 16.1.85			
DGCA / PT-6A / 13	RENEWAL OF THE COMPRESSOR DELIVERY AIR LINE (P3) FITTER ASSEMBLY	FAA AD 92-15-11	'AS IN AD'	'AS IN AD'
DGCA / PT-6A / 14	TO PREVENT ENGINE FAILURE AND INFLIGHT ENGINE SHUT DOWN	FAA AD 95-13-08	'AS IN AD'	'AS IN AD'
DGCA / PT-6A / 15	ENGINE - COMPRESSOR BLEED OFF VALVE - INSPECTION/ REPLACEMENT	TC AD CF 96-24 & TC AD CF 99-23	'AS IN AD'	'AS IN AD'
DGCA / PT-6A / 16	PT6A ENGINE SERIES -- INSPECTION OF TURBINE EXHAUST DUCT	TC AD CF 2002-47	'AS IN AD'	'AS IN AD'
DGCA / PT-6A / 17	INSPECTION OF THE ACCESSORY GEAR BOX COUPLING SHAFT LOCKBALL	TC AD CF 2001-41	'AS IN AD'	'AS IN AD'
DGCA / PT-6A / 18	TO PREVENT FAILURE OF THE SHAFT PORTION OF THE SUN GEAR, WHICH WOULD RESULT IN AN ENGINE IN-FLIGHT SHUT DOWN, POSSIBLE UNCONTAINED ENGINE FAILURE, AIRCRAFT DAMAGE, AND SERIOUS INJURIES	FAA AD 2011-20-51	'AS IN AD'	'AS IN AD'